## CATERPILLAR\*

## Service Report

UNIEN	ITILLA	ın			SCIVI	CC 1	Серогс							
					Report Hea	der i	Informatio	m						
Wo	ork Order	WP81850			Dealer Cod	de E	44				Manufacturer	TE		
Emp	oloyee ID	2618			Service Da	te 7	/11/2018				Model	9205		
C	Customer	ACT LIMITED	LLC	Equipr	Custom ment Numb						Customer PO			
Serial	Number	925000406												
	SMU	10069 Hours	S	Equipn	nent Locatio	on Z	IEGLER REE	BUIL	D CEN	TER				
	IN Date	7/17/2018			Promise Dat	te					OUT Date	7/26/	2018	
Inst	tructions													
					Truck I	nfor	mation			199				
	Tr	uck Make							Truck	k Mod	el			
		VIM							Ca	ь Тур	oe e			
	Vehic	cle Config							Delive	ry Dat	te 1/15/200	8		
egment (	Part Number Operation No	Part Name	Qty Date	SMC		.abor La	Secondary	N C P	Group Jumber Contain Fart	ing	Group Name	Produ Inope	erable?	CAT Item
					Miscella	neou	s Costs							
	Operation No	Employee ID	D	ate	ate Charge Codes Qty De		Desc	escription Cost						
					Mi	leag	e							
	Operation No	Employee ID		Vehi	cle		Date			C	Charge Codes		Dist	ance
					Repair B	Backg	ground							
Segment No	o: 20													
	Customer	Complaint												
	Cause	e of Failure												

Resultant Damage	
Repair Process Comments	ASSEMBLED ENGINE USING CAT REMAN LONG BLOCK PN# 10R-9650 WITH ALL NEW GASKETS/SEALS. CLEAN, REPAIR/REPLACE ALL PARTS AS NECESSARY. THE ENGINE WAS DYNAMOMETER TESTED TO VERIFY PERFORMANCE AND FACILITATE PROPER BREAK IN. THE ENGINE PRODUCED 429 HP @ 2100 RPM. HP SPEC IS 426 HP @ 2100 RPM. THE ENGINE WAS ACCESSORIZED AND PAINTED.

Customer Signature	Technician Signature

Workorder Closing					
No Answer	Is the Job Completed?				
No Answer	Are unused parts being restocked?				
No Answer	Is a Reman core being returned?				
No Answer	Is this a warranty job?				
No Answer	Are warranty parts being returned?				
No Answer	Are checked-out tools being returned?				
No Answer	Has the information been entered to SIMS?				

Additional Opportunities					
No Answer	Is there Additional Service to be done?				
No Answer	Did the customer request a quote for additional service?				
No Answer	Did the customer request a PSSR to contact them?				
Comment					

Parts Parts							
Segment No	Ord∈r ID	Work Order	Operation	Additional Notes			

Application Data						
Application	Report	Created				

File Attachments					
Name	Size	Modified	Title	Description	
ENGINE BEARING DATE CODE CHECK LIST.xls	29184	7/24/2018 8:07 AM			
LGK00763_PSRPT_2018-	<b>%74&amp;76</b> 8_10.29.44.pdf	7/26/2018 10:29 AM			
WP81850 DYNO REPORT.pdf	241623	7/26/2018 12:05 PM			

File Attachments				
Name	Size	Modified	Title	Description
WP81850 FINAL IDLE.png	247582	7/26/2018 9:32 AM		
WP81850 FULL LOAD.png	247020	7/26/2018 6:44 AM		
WP81850 HALF LOAD.png	247881	7/26/2018 6:05 AM		
WP81850 INITIAL IDLE.png	244794	7/26/2018 5:36 AM		
WP81850 TORQUE CHECK.png	250742	7/26/2018 9:14 AM		
ENGINE MOF CHECK LIST.xls	130560	7/27/2018 1:44 PM		

Digital Images

Digital Images		
	Title:	
	Description:	
	7/24/2018 8:07 AM	

Digital Images			
	Title:		
	Description:		
		7/26/2018 10:29 AM	

Digital Images		
	Title:	
	Description:	
	7,	/26/2018 12:05 PM











Digital Images			
	Title:		
	Description:		
	·	7/27/2018 1:44 PM	