

Larry's Welding, LLC.

1381 130th St.

Emerson, IA. 51533

Phone: 712-825-2607 Fax: 712-825-9182

INVOICE

1153

Org. Est. # 000343

Invoice from History

Work Completed : 03/09/2017

Date: 08/28/2018

Larrys Welding - Larrys Welding

1381 130th St

Emerson, IA 51533

Home

2003 Peterbilt - 379 - C15 6NZ76925

Lic # :

Odometer In : 484052

Unit # : 2193

VIN # : 1XP5DB0X0 3N594758

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
Dipstick P/S Q347137	1.00	26.47	26.47	fan clutch	382.50
Mod Valve Kit R950140	1.00	315.28	315.28	r and i fan clutch and rebuild	
Fan Clutch Kit 14-256	1.00	585.00	585.00	LH step broke	
Shaft Lock 590749	4.00	9.22	36.88	Rh hood hinge broke	
Case Lock 590751	4.00	9.10	36.40	RD shocks	
Door Lock Kit 23-08599	1.00	136.26	136.26	Rh door latch and tumbler	
V-Clamp 1010-1	1.00	27.46	27.46	LH windshield	
Mount Bushing Radiator 07-05861-2	2.00	40.77	81.54	flex@ turbo	
Bushing 14-14656-4	4.00	23.72	94.88	adj. clutch a+b	
Bulk Oil 15W40	9.00	14.95	134.55	drive abs valve leaking air	
Adapter 143737	1.00	2.96	2.96	air filters	
Valve 1/2 90602	1.00	3.84	8.84	engine fan stuck on	
1/2 45 degree st l 6kh97a	1.00	0.00	n/c	draglink	
1/2 pipe nipple 9p660b	1.00	0.00	n/c	loose belts	
1/2 pipe tee 6p478a	1.00	0.00	n/c	slight miss, #1 injector dead	
Ujoint 1710 5-0280	1.00	56.83	56.83	radiator support bushings rear	
U-joint 6-0676	1.00	132.61	132.61	rear crossmember plate bent and loose	
Isolator K3399	1.00	24.33	24.33	ac inop	
Blower Motor SR2000010	1.00	107.76	107.76	blower motor excessively loud	
Drag Link MPGS-E393	1.00	213.33	213.33	hvac levels not changing	
5" Exhaust Clamp H500P	1.00	6.70	6.70	lower radiator tube rusted thin and leaking	
				RH fuel tank loose	
				lot/dot	170.00
				lot dot, notice engine miss, diag #1 injector dead	
				find vibration	1,147.50
				checked everything for play, tightened yolks, found 3rd member play	
				pulled 3rd member tore apart found nothing out of the norm	
				reinstalled jacked up checked all found input shims in front bearing	
				to much play removed shims and hoked up all sensors for a drive u	
				know the rest.	
				left fuel shut off broken off	63.75
				replace shut oof wih ball valve	
				fuel tee leaking	85.00
				replace tee	
				#1 injector	382.50
				replace #1 injector and adjust	
				R&I 2 u joints and tighten yoke nut and add red locite,	153.00
				grease u joints	
				gear shift loose	297.50
				remove gear shift cover all bolts siezed cut of heads and	
				extract,replace shift lever isolator	
				blower motor noisy	127.50
				replace blower motor	
				R&I draglink	76.50
				replace drag link	
				exhaust	340.00
				repace flex pipe between turbo and and down pipe	
				replace muffler and guard replace flex pipe to muffler replace	
				down pipe elbow-used	

Visit us on the web : www.larrysjettrailers.com

Larry's Welding, LLC.

1381 130th St.

Emerson, IA. 51533

Phone: 712-825-2607 Fax: 712-825-9182

INVOICE

1153

Org. Est. # 000343

Invoice from History

Larrys Welding - Larrys Welding

1381 130th St

Emerson, IA 51533

Home

Work Completed : 03/09/2017

Date: 08/28/2018

2003 Peterbilt - 379 - C15 6NZ76925

Lic # :

Odometer In : 484052

Unit # : 2193

VIN # : 1XP5DB0X0 3N594758

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
5" Step Clamp 9624	5.00	14.07	70.35	replace front shocks	153.00
Flex Pipe 5" SS 8888	7.00	20.47	143.29	replaced both front shocks and tighten mounting pins	
Nut USS Size: 3/8-16 GRD5 40134	4.00	0.12	0.48	lower radiator pipe leak	127.50
Washer Size: 3/8 76003	48.00	0.12	5.76	remove lower pipe cut off bracket and replace hoses	
Lock Nut 3/8-16 57110	4.00	0.28	1.12	upper radiator support brace bushings	63.75
Bolt USS 3/8x2-1/2 grd 5 20154	4.00	0.68	2.72	replace upper support rod bushings	
Shock Steer 65405	2.00	84.53	169.06	torque arms	187.00
3 inch radiator hose 5515300c	1.50	0.00	n/c	replace both torque arms	
clamp 325	1.00	0.00	n/c	replace spring wear pads	850.00
Mount Bushing Radiator 07-02552	4.00	12.22	48.88	replace all spring pads - all bolts were frozen and had to heat and cut bolts	
Torque Arm TMR551	2.00	212.75	425.50	replace drive shocks	63.75
Spring Pad M1751	4.00	94.60	378.40	Installed far rear shocks	
Shock Drive 85311	4.00	64.03	256.12	clutch and clutch brake	127.50
Freon per lb R134A	3.00	10.00	30.00	adjust clutch	
Actuator MA0200-01S	1.00	225.01	225.01	air filters	76.50
2- butt connectors -2-male spade connectors 0000	0.00	0.00	n/c	replace both air filters	
Clock PP604225	1.00	43.28	43.28	radiator bushings	42.50
Sand - 50lb Bags 189-1344	27.00	9.78	264.06	replaced top rod radiator bushings	
Grille Size: PETE 379 PG0161	1.00	360.00	360.00	cross rear	170.00
Chrome Grille Surround Size: 379 PG0260B	1.00	585.00	585.00	replace cross rear modify and drill new mounting holes	
Fender Pete 379 Size: LH FN4905L	1.00	464.48	464.48	air cond in op. / blower fan stuck on defrost	170.00
				low on freon recovered 1lb 6 oz.evacuate and recharge. Lance troubleshot airflow issue, discovered and R2'd blend-door servo motor	
				frd brake	178.50
				replace brake shoes right front drive axle	
				tail lights	170.00
				rewire tail lights and mount to new rear cross	
				guage inndash missing	63.75
				remove dash panel clock was broken out replace clock and rewire	
				hose on cac has hole in it	51.00
				replace cac hose and clamp	
				modify crossmember	25.50
				cut tabs grond smooth so fit on truck on rear	
				single out rear wheels	59.50
				removed rear wheels put scabs on for blasting frame	
				blast frame	357.00
				prepped and blasted frame	
				prep for sandblast	63.75
				get parts	59.50
				got step peace by headlight and two air horns	
				sand	1,381.25

Visit us on the web : www.larrysjettrailers.com

Larry's Welding, LLC.

1381 130th St.

Emerson, IA. 51533

Phone: 712-825-2607 Fax: 712-825-9182

INVOICE**1153**

Org. Est. # 000343

Invoice from History

Work Completed : 03/09/2017

Date: 08/28/2018

Larrys Welding - Larrys Welding

1381 130th St

Emerson, IA 51533

Home

2003 Peterbilt - 379 - C15 6NZ76925

Lic # :

Odometer In : 484052

Unit # : 2193

VIN # : 1XP5DB0X0 3N594758

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
Fender 379 Aluminum Size: RH FN4905R	1.00	464.48	464.48	sand cab and hood	
Headlight Round Pete 379 Size: UP 31758	1.00	205.31	205.31	install strikers	255.00
Striker Pin MPGS-21200	2.00	33.40	66.80	install strikers and misc	
Mount Pivot Size: LH L48-6026	1.00	118.40	118.40	prep for paint	1,763.75
Mount Pivot Size: RH L48-6026R	1.00	118.40	118.40	prep for paint	
Pivot Bolt Sleeve 13-04727	2.00	48.60	97.20	paint motor	425.00
Hood Pivot Bushing MPGS-20896	1.00	26.50	26.50	prep for paint. paint yellow	
Hood Pivot Bolt MPGS-21319	2.00	44.06	88.12	paint frame	616.25
Headlight Bracket Aftermarket Size: 379 PETE PAIR 009-01	1.00	477.09	477.09	paint frame	
Door Seal R60-6001-650	1.00	103.63	103.63	prep motor	233.75
used air horn 1111	2.00	0.00	n/c	prep for paint	
Air Horn Spacer 18-02906	4.00	37.50	150.00	install hood and grill	680.00
Air Horn Gasket 18-02958	4.00	5.60	22.40	prep hood for paint. put on frame and install grill	
used step peace under headlight pass side 1111	1.00	0.00	n/c	hood	637.50
Chrome Mudflap Hanger Size: UP 11300	1.00	108.85	108.85	assemble hood and spray undercoat	
Bolt SAE 1/2x2 grd 5 21200	2.00	1.16	2.32	install hood	170.00
rivnut 89031	8.00	0.00	n/c	put hood on truck and move bumper	
Visor w/Door Mounted Mirrors 35024RW	1.00	503.75	503.75	prep for paint	361.25
Chassis Saver Size: OZ UCP99	20.00	2.58	51.60	sand	
Reducer Size: OZ S8	3.00	0.80	2.40	primer	403.75
Frame Paint Size: OZ	48.00	1.52	72.96	mask and spray primer	
				prep for primer	2,252.50
				mask for primer	
				spray primer	
				spot puddy and sand primer	
				mask	
				clean and spot prime	
				mix paint	
				untape and assemble fenders brackets mirrors and window	
				assemble exhaust	
				paint cab air bag mount	
				install bumper	
				prep for primer	
				mask for primer	
				spray primer	
				spot puddy and sand primer	
				mask	
				clean and spot prime	
				mix paint	
				untape and assemble fenders brackets mirrors and window	
				assemble exhaust	
				paint cab air bag mount	
				install bumper	
				polish chrome	510.00
				glue trim	
				clean cab	
				scotchbrite	

Visit us on the web : www.larrysjettrailers.com

Larry's Welding, LLC.
 1381 130th St.
 Emerson, IA. 51533
 Phone: 712-825-2607 Fax: 712-825-9182

INVOICE

1153

Org. Est. # 000343

Invoice from History

Larrys Welding - Larrys Welding

1381 130th St
 Emerson, IA 51533
 Home

Work Completed : 03/09/2017

Date: 08/28/2018

2003 Peterbilt - 379 - C15 6NZ76925

Lic # :

Odometer In : 484052

Unit # : 2193

VIN # : 1XP5DB0X0 3N594758

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
77410				polish chrome	
Chassis Activator Size: OZ	6.00	33.92	203.52	glue trim	
77132				clean cab	
Grille Trim	1.00	0.00	n/c	scotchbrite	
m134708l				paint	2,783.75
Grille Trim	1.00	0.00	n/c	sand primer	
m134708r				tape and mask	
Hood Bumper	2.00	26.28	52.56	paint and assemble	
HM75-65711				paint	
Door Handle 379 Size: LH	1.00	80.43	80.43	sand primer	
HLK1066				tape and mask	
Door Handle 379 Size: LH	1.00	80.43	80.43	paint and assemble	
HLK1065				polish mirror, air cleaners and exhaust heat guards	148.75
Hood Latch	2.00	38.73	77.46	use steel wool and polish	
L56-0001				remove headliner to hook up air horns	1,997.50
Hood Holddown	2.00	24.72	49.44	paint int	
L03-0001				assemble int and clean	
Primer Size: OZ	144.00	1.50	216.00	polish tanks air tanks battery box and wheels	
2253				instal door and window seals	
Hardner Size: OZ	16.00	3.30	52.80	put on reflectors	
20:30				remove headliner to hook up air horns	
Reducer Size: OZ	56.00	0.60	33.60	paint int	
16101				assemble int and clean	
Exhaust Clamp Prefom Size: 5	1.00	9.82	9.82	polish tanks air tanks battery box and wheels	
20S-500				instal door and window seals	
door latch	1.00	0.00	n/c	put on reflectors	
mpg522005				remove headliner to hook up air horns	
Bolt USS 3/8x1-1/2 grd 5	12.00	0.44	5.28	paint int	
20150				assemble int and clean	
Bolt Size: 3/8 X 2 USS GRD5	12.00	0.56	6.72	polish tanks air tanks battery box and wheels	
20152				instal door and window seals	
Lock Nut Size: 3/8-16	16.00	0.16	2.56	put on reflectors	
42110				Turn signals dim, flash on 4-ways but not separately	63.75
Bolt USS 1/2x1-1/2 grd 5	8.00	0.80	6.40	Troubleshoot; discovered & R2'd faulty flasher	
20198				Steering shaft u-joint worn	136.00
Locknut 1/2-13	8.00	0.36	2.88	R2'd u-joint	
42114				2nd from left clearance marker inop	17.00
Washer Size: 1/2	14.00	0.24	3.36	R2'd bulb	
76005				Eng oil 1 gal low	21.25
Bolt USS 1/4x1-1/2 Size: 1/4 X 1-1/2	6.00	0.24	1.44	Topped off eng oil	
G5				Turbo worn, passing lots of oil	n/c
20106				Remove current air lines from protection valve and	
Locknut 1/4-20	6.00	0.12	0.72	move catwalk further back; install POGO and plumb in	106.25
				new hoses/trlr cord	
				Relocated catwalk, mounted POGO, plumbed in air lines and	
				connected trlr cord.	
				Tighten exh clamp under passenger door	8.50
				Tightened	
				Adj brakes	21.25
				adjusted brakes	
				Secure fuel lines along center right frame rail	17.00
				Secured hoses	
				Fuel gauge inop.; ordered left sending unit	n/c

Visit us on the web ; www.larrysjettrailers.com

Larry's Welding, LLC.
 1381 130th St.
 Emerson, IA. 51533
 Phone: 712-825-2607 Fax: 712-825-9182

INVOICE

1153

Org. Est. # 000343

Invoice from History

Larrys Welding - Larrys Welding

1381 130th St
 Emerson, IA 51533
 Home

Work Completed : 03/09/2017

Date: 08/28/2018

2003 Peterbilt - 379 - C15 6NZ76925

Lic # :

Odometer In : 484052

Unit # : 2193

VIN # : 1XP5DB0X0 3N594758

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
42106					
Washer Size: 1/4 76001	12.00	0.08	0.96	Discovered right tank electrical plug disconnected; re hooked. Also the left tank wiring has been pulled out of sending unit. ORDERED SENDER	
window mt mirrors 35024	1.00	0.00	n/c	Needs blue glad-hand	n/c
Headlight Round Pete 379 Size: UP 31758	2.00	205.31	410.62	Give good look over Inspected; listed items as separate entries	34.00
Headlight Bracket Aftermarket Size: 379 PETE PAIR 009-01	2.00	477.09	954.18	clean floor install seat and air line paint floor paint bumper brackets install hub caps	n/c
Glove Box Cable 17-04310-215	2.00	16.17	32.34	clean floor install seat and air line paint floor paint bumper brackets install hub caps	
Primer Size: OZ 2253	80.00	1.50	120.00	Wire in headlights/fwd turn signals Wired in lighting	191.25
hardner 2030	20.00	0.00	n/c	Overhaul	3,306.50
paint blk012	115.00	0.00	n/c	remove head, inspect found head is cracked between exhaust valve on 5 of the 6 cylinders. Overhauled and reassembled.	
Hardner Size: OZ LHF	32.00	3.66	117.12		
Recucer Size: OZ LR11	64.00	0.68	43.52		
Door Seal 20-15238	1.00	35.60	35.60		
Glass Channel 20-08108	1.00	33.58	33.58		
Glass Channel Run 75000525	1.00	48.28	48.28		
Window Crank Spring 20-18487	2.00	4.36	8.72		
Glove Box Cable 17-04310-215	2.00	16.17	32.34		
cup holder insert 17-04304	1.00	0.00	n/c		
Chrome Hub Cover 10263up	4.00	49.96	199.84		
Front Hub Cap 205CD	2.00	8.30	16.60		
Lug Nut Cover 33MM Push 18200AC	20.00	2.18	43.60		
Flasher Size: 2 PRONG 44690	1.00	19.72	19.72		
U-Joint	1.00	12.85	12.85		

Visit us on the web : www.larrysjettrailers.com

Larry's Welding, LLC.

1381 130th St.

Emerson, IA. 51533

Phone: 712-825-2607 Fax: 712-825-9182

INVOICE**1153**

Org. Est. # 000343

Invoice from History

Work Completed : 03/09/2017

Date: 08/28/2018

Larrys Welding - Larrys Welding

1381 130th St

Emerson, IA 51533

Home

2003 Peterbilt - 379 - C15 6NZ76925

Lic # :

Odometer In : 484052

Unit # : 2193

VIN # : 1XP5DB0X0 3N594758

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
1-0170					
Mini Lamp	1.00	0.84	0.84		
912					
Electric/Air Line Assembly 3 in 1	1.00	216.38	216.38		
Size: RUBBER					
30-2171					
Street L. Size: 1/2 X 45	2.00	3.50	7.00		
98033					
Elbow Size: 1/2 90D	1.00	2.64	2.64		
98023					
Gladhand Red	1.00	6.52	6.52		
12-008					
Pogo Stick	1.00	62.62	62.62		
17-0400					
Fuel Sender	1.00	298.45	298.45		
5549-13715-26					
Split Loom Size: 5/8	11.00	1.60	17.60		
75104					
Butt Connector Blue Nylon Size:	12.00	0.28	3.36		
16-18					
71225-1					
Burr Connector Yellow Nylon	2.00	0.36	0.72		
71226-1					
Wire Size: 14G BLK	2.00	1.36	2.72		
71392-6					
Connector Blue Ring Size: 1/4	2.00	1.28	2.56		
71204-1					
Tie Nylon 14-1/2 Narrow	18.00	1.88	33.84		
71386					
Rubber Clip Size: 5/8	2.00	1.68	3.36		
74824					
4 Way Trailer Wire	9.00	1.96	17.64		
49905					
Oil Filter	1.00	17.19	17.19		
B99					
Bulk Oil	12.00	14.95	179.40		
15W40					
Antifreeze Green Full Strength Size:	1.00	11.69	11.69		
GALLON					
87676					
1 1/2" black radiator hose...per inch	2.75	0.00	n/c		
0004					
Engine Kit Size: C15	1.00	2,845.92	2,845.92		
FPIFKC15					

Visit us on the web : www.larrysjettrailers.com

Larry's Welding, LLC.
 1381 130th St.
 Emerson, IA. 51533
 Phone: 712-825-2607 Fax: 712-825-9182

INVOICE

1153

Org. Est. # 000343

Invoice from History

Larrys Welding - Larrys Welding
 1381 130th St
 Emerson, IA 51533
 Home

Work Completed : 03/09/2017

Date: 08/28/2018

2003 Peterbilt - 379 - C15 6NZ76925

Lic # :

Odometer In : 484052

Unit # : 2193

VIN # : 1XP5DB0X0 3N594758

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
Cylinder Head 20R2645	1.00	3,920.00	3,920.00		
Thermostat 2477133	2.00	64.87	129.74		
Gasket 1393550	1.00	8.52	8.52		
Gasket 4N1156	1.00	3.26	3.26		
Seal 1262702	1.00	12.99	12.99		
Seal 1986068	1.00	12.27	12.27		
O'ring 1142687	1.00	6.80	6.80		
Seal 6V5266	1.00	13.39	13.39		
O'ring 1367226	1.00	7.24	7.24		
Stud 1061792	11.00	17.20	189.20		
Stud 1061793	1.00	15.05	15.05		
Locknut 1687800	12.00	3.56	42.72		
Turbo Gasket 1S4295	1.00	10.83	10.83		
Bolt 2N2765	4.00	14.65	58.60		
Lock Nut 2N2766	4.00	9.46	37.84		
Seal Injector 2303775	6.00	12.90	77.40		
Seal Injector 2303728	6.00	9.92	59.52		
Seal 9X7317	6.00	6.06	36.36		
Exhaust Sleeve 2818261	6.00	34.85	209.10		
Seal 1607271	1.00	56.10	56.10		

Larry's Welding, LLC.

1381 130th St.

Emerson, IA. 51533

Phone: 712-825-2607 Fax: 712-825-9182

INVOICE**1153**

Org. Est. # 000343

Invoice from History**Larrys Welding - Larrys Welding**

1381 130th St

Emerson, IA 51533

Home

Work Completed : 03/09/2017

Date: 08/28/2018

2003 Peterbilt - 379 - C15 6NZ76925

Lic # :

Odometer In : 484052

Unit # : 2193

VIN # : 1XP5DB0X0 3N594758

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
---------------------------	-----	------	-----	-------------------	-----

Org. Estimate	44,662.97	Revisions	0.00	Current Estimate	44,662.97
---------------	-----------	-----------	------	------------------	-----------

Labor:	24,828.50
Parts:	19,834.47
SubTotal:	44,662.97
Tax:	0.00
Total:	44,662.97
Bal Due:	\$0.00

[Payments - Cash - \$44,662.97]

Like us on Facebook and get a discount on your next purchase

Vehicle Received: 3/9/2017

Customer Number : 1334

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature _____

Date _____

Visit us on the web : www.larrysjettrailers.com