

EQUIPMENT INSPECTION

Equipment Inspection Location: 22904 West Southern Avenue, Buckeye, Arizona

Inspection Item: 1

Inspection Date: June 17, 2019

Description: 2015 Claas Jaguar 980 Forage Harvester

Serial Number: 49700315

Hours: 3563 Metered Hours Cutter Hours: 2813 Metered Hours

General Description: Cab, 884-HP Diesel Engine, Hydrostatic Transmission, 36-Knife Drum, Rear Discharge Chute, 900/60R32 Tires.

Cab: Interior is in overall good condition. No apparent odor and not excessively dirty.

Exception: (1) burn hole in buddy seat. Vent cover is hanging loose on the ceiling of the cab. Small dash panel missing.

Cab Glass: Good Condition. No chips or cracks.

Cab Systems and Components: Good Condition. Trimble FM-750 GPS System is functioning and maintained. No warning dash lights displayed. Interior lights functioning. A/C and heat in operating order.

Engine: 884-HP Diesel Engine. Readily starts and shuts down crisply.

Transmission: Hydrostatic. Seemed to shift properly.

Cutter Component: 36-Knife Drum - Average wear. Replaced knives in 11/2018. Replaced rollers 11/2018

Tires: 900/60R32 Tires. Good Condition. No side wall damage. Approx. 80% to 75% tread remaining.

Exterior Condition: Average Condition. Front right side of cab door has cracked plastic panel. Some exterior rust and chipped paint. Minimal rust on chute. Left side by ladder has some gauges/dents in the plastic panel, as well as paint scratches on the steel ladder. Exterior lights functioning properly.

Overall Condition: Good to Average Condition. This unit appears to run, drive and operates as it was manufactured to do with no apparent fluid and or gas leaks. No modifications, upgrades or rebuilds for this unit.

Maintenance: This unit has received regular preventative maintenance. Maintenance records are shared in Exhibit B.

Estimate of Repairs: Not available.

Inspector Notes: The cracked plastic panel will need to be replaced and some paint touch up will need to be completed.