

EQUIPMENT INSPECTION

Equipment Inspection Location: 22904 West Southern Avenue, Buckeye, Arizona

Inspection Item: 3

Inspection Date: June 17, 2019

Description: 2015 Claas Orbis 900 Rotary Forage Harvester Head

Serial Number: 99201440

Hours: N/A

General Description: 12-Row, 30' Wide, Hydraulic Folding Wings

Exterior Condition: Average Condition. Cutter wheels and side augers show normal wear. Rust on the bottom side of the unit. Crack in one plastic side panel.

Mechanical Condition: Average Condition. Some of the cutter wheels have been replaced and are in good condition.

Overall Condition: Good to Average Condition. This unit seemed to operate as it was manufactured to do.

Maintenance: This unit has received regular preventative maintenance. Maintenance records are shared in Exhibit B.

Estimate of Repairs: Not available.

Inspector Notes: The serial number of this unit does not match the serial number that was provided by Wells Fargo. Personnel of Crane Equipment stated that this was the unit that was received with the Claas 980 Forage Harvester SN# 49700315.