

EQUIPMENT INSPECTION

Equipment Inspection Location: 22904 West Southern Avenue, Buckeye, Arizona

Inspection Item: 2

Inspection Date: June 17, 2019

Description: 2015 Claas PU380 Pickup Head

Serial Number: 13503044

Hours: N/A

General Description: 13' Wide, 24" Dia. Auger, Dual Roller, Guide Wheels

Exterior Condition: Average Condition. Average paint scratches on the auger, rollers and tines. Average wear on feed roller and teeth.

Mechanical Condition: Average Condition. Operates as it was manufactured to do.

Tires: Average Condition. No side wall damage. Approx. 75% tread remaining.

Overall Condition: Average Condition. This unit seemed to operate as it was manufactured to do with no apparent fluid leaks.

Maintenance: This unit has received regular preventative maintenance. Maintenance records are shared in Exhibit B.

Estimate of Repairs: Not Available

Inspector Notes: Average condition. All components seemed to operate as they should.