

CASE 3540

UNIT: YGT043064

[View Asset](#)









GENERAL APPERANCE

UID	YGT043064	Paint	No visible damage
Glass	No visible damage or missing components	Exterior Lights	All lights operational
Steps/Ladders	Good	Serial Number / VIN	YGT043064

CONTROL STATION SPRAYER

Operator Station 2955 Machine Hours Showing, Automatic, Air Conditioner, Air Ride Seat	Precision Farming	Raven Display
---	--------------------------	---------------

SAFTEY

Horn	Operational	Seat Belts	Operational
-------------	-------------	-------------------	-------------

CONTROL STATION

Seats/Armrests	No visible damage or missing components	Hydraulic Controls	Good
Steering Control	Good	Drivetrain Controls	Good
Oil Pressure	The gauge registers in the operating range.	Warning Lights	Operational
Guages	Operational	Hour Meter/Odometer (Start)	2955.6 hrs

Hour Meter/Odometer 2955 hrs

Cab Heater Operational

Cab Air Conditioner

The ambient temperature is too cold to check

Limited Function Check

The main components are in place and operational as noted.

ENGINE

Blow By Visible

Exhaust System
No visible damage or missing components

Starter Operational

Radiator Good

Oil Leaks No dripping leaks

DRIVETRAIN

Transmission Good

Limited Function Check The drivetrain was operational.

Rear Axle Good

HYDRAULICS

Hydraulic Pump Good

Hydraulic Tank Good

Cylinder Pins and Bushings Condition Good

Hydraulic Motors Not operationally checked

Cylinders Good

Limited Function Check (Hydraulics)
The hydraulic system was operational.

CHASSIS SPRAYER

Body Details

Pump Type:, Hydraulic Driven Pump, 2000 L Tank Type:
Stainless Steel Tank, Foam Markers, Rinse Tank, 5 Section
Control

Booms and Boom Tree Good

Boom Shocks Good

Tank Good

Plumbing Good

Tank Saddle Good

Air System Not operationally checked

Foam Marker Not operationally checked

Controller Rating Appears complete

CHASSIS RUBBER TIRE AG

Steering Linkage Good

Park Brake Good

Limited Function Check (Brakes)

Frame Condition Good

The brake system functioned, stopping and holding the machine.

Wheel Condition

Good

Wheel Studs, Nuts, Lugs

Good

TIRE SIZE: 1050/50R32

38_{/32}

N/A

N/A

N/A
N/A

N/A
N/A

TIRE SIZE: 1050/50R32

28_{/32}

N/A

N/A

24_{/32}

N/A
N/A

N/A
N/A

RECONDITIONING

Paint Rusted/Damaged

\$500

Total

\$500

Too Cold to Test A/C

UNIT SPECS

Customer

Wells Fargo

INSPECTION LOCATION

CURRENT LOCATION

VERSION HISTORY

02/09/2022