



SERVICE INVOICE

www.plattevalleyequipment.com

Invoice To Acco	ice To Account No:			SERVICE INVOIC			
Internal Used	Stock No. 560826			Invoice N	umber:	2364551	
			: 	Invoid	ce Date:	5/13/2020	
ı				L	ocation:	30	
				Work Order N	Number:	418662	
				Payme	nt Type:	Account	
Bus Phone:							
Prv Phone:		Mob Phone:			Page:	1 of 2	
Deliver To:							
Internal Used	Stock No. 560826			Make/Model:	JOHN DEERE PDRV/2WD/650X85	R38DLS/750X65F	
				Meter:	1475		
•			u de la constante de la consta	Serial Number	: 1H0S690SAG07853	41	
Bus Phone:				Eq ID:	SAG0785341		
Prv Phone:		Mob Phone:		Fleet No:			


PVE-COMBINE Internal

COMPLAINT:

01 Pro-Active combine inspection

Part Number	<u>Description</u>	Quantity 2.00	List Price	Net Price	Extended Price	Taxed Ind
KENSOL	BRAKE/METAL CLE		3.60	3.60	\$7.20	N
<u>Miscellaneous</u>	<u>Description</u>	Quantity	List Price	Net Price	Extended Price	Taxed Ind







SERVICE INVOICE

www.plattevalleyequipment.com

Invoice To Account No: 4	SERVIC	E INVOICE
WARRANTY CUSTOMER	Invoice Number:	2364554
John Deere Warranty	Invoice Date:	5/13/2020
	Location:	30
	Work Order Number:	418662
	Payment Type:	Account
Bus Phone:		4
Prv Phone: Mob Phone:	Page:	1 of 1
Deliver To:		
PLATTE VALLEY EQUIPMENT CO 2221 COUNTY ROAD Q	Make/Model: JOHN DEERE PDRV/2WD/650X	85R38DLS/750X65R
PO BOX 1060	Meter: 1475	
FREMONT NE 68025	Serial Number: 1H0S690SAG078	5341
Bus Phone: (402)721-9111	Eq ID: SAG0785341	
Prv Phone: (800)844-8818	Fleet No:	

PIP18HX556A Warranty

COMPLAINT:

02 18HX556 A - 13.5L ENGINE HEAD GASKET LEAK - FIX AS FAIL

CORRECTION:


Labor: \$75.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$7	5.00
				Labor:	\$75.00
				Parts:	\$0.00
				OL&M:	\$0.00
				Misc:	\$0.00
				Sales Tax:	\$0.00
* * * DOCUME	NT COPY * * *			Grand Total:	\$75.00

TERMS AND CONDITIONS

Unused parts in new condition are returnable within 30 days of purchase and must be accompanied by this invoice. Returned parts are subject to a minimum 25% restocking fee. Open kits or electrical parts are not returnable. Please refer to our return policy for full details. Thank you for your business.

Received by:	Date:
received by	







Invoice To Account No:		SERV	ICE INVOICE
Internal Used Stock	No. 560826 (Sold)	Invoice Number:	2450917
		Invoice Date:	7/15/2020
		Location:	30
		Work Order Number:	422060
		Payment Type:	Account
Bus Phone:			
Prv Phone:	Mob Phone:	Page:	1 of 44
Deliver To:			
Internal Used Stock	No. 560826 (Sold)	Make/Model: JOHN DEERE	
PLATTE VALLEY EQI		PDRV/2WD/65	0X85R38DLS/750X65F
2221 COUNTY ROAD	Q	Meter: 1409	
PO BOX 1060 FREMONT NE 6802	5	Serial Number: 1H0S690SAG0	1785341
TIVE WOOM INC. 00023	5		77 00041
Bus Phone:		Eq ID: SAG0785341	
Prv Phone:	Mob Phone:	Fleet No:	

//S690 CMBS695 Internal

COMPLAINT:

01 Hook up Service Advisor laptop & install latest software

CORRECTION:

Hook up Service Advisor laptop & install latest software

CASHDISC	CASH DISC ALLOWED	01.088	40.00	1.00	0.00	-4,000.00	(\$4,000.00)	IN
Labor: \$240.00	Parts: \$0.00	OL&M:	\$0.00	Wilsc:	(\$4,000.00)	Sup-10	otal: (\$3,760.0	00)

Gen2- Internal

COMPLAINT:

Replace cracked inspection door

CORRECTION:

Removed bolts and clamps removed inspection door and installed new installed clamps and hardware


<u>Part Number</u>	Description		Quantity	List Price	Net Price	Extended Price	Taxed Ind
H233711	DOOR		1.00	36.11	36.11	\$36.11	N
Labor: \$37.50	Parts: \$36.11	OL&M: \$0.00	Misc: \$	0.00	Sub-To	tal: \$73.61	

//S690 CMBS733 Internal

COMPLAINT:

03 Feeder house drive chain (RH), R&R (includes chain & both sprockets)







Invoice To Acco	
Internal Used	Stock

SERVICE INVOICE

Internal Used Stock N	lo. 560826 (Sold)	Invoice Number:	2450917
		Invoice Date:	7/15/2020
		Location:	30
-		Work Order Number:	422060
		Payment Type:	Account
Bus Phone:			
Prv Phone:	Mob Phone:	Page:	2 of 44

Deliver To:

Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO 2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Mob Phone:

Make/Model:

JOHN DEERE

PDRV/2WD/650X85R38DLS/750X65R

Meter:

1409

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

//S690 CMBS733 Internal

CORRECTION:

Feeder house drive chain (RH), R&R Removed shield Cut old chain and removed and discarded Removed old sprockets and installed new freed up lower splined shaft sprocket installed new chain and adjusted installed shield

	Part Number AXE19940	Description IDLER SPRO	Quantity 2,00	List Price 36.05	Net Price Extended Price 36.05 \$72.10		Taxed Ind N
	AXE80368	link chain, #60H, 181 LINKS	1.00	158.90	158.90	\$158.90	N
,	Labor: \$225.00	Parts: \$231.00 OL&M: \$0	0.00 Misc:	\$0.00	Sub-Total	: \$456.00	

//S690 CMBS155 Internal

COMPLAINT:

04 Feeder house lower RH shaft bearing, Replace

CORRECTION:

Feeder house lower RH shaft bearing, Replace Removed tone wheel removed sensor bracket removed shaft and bearing housing removed shaft seal cut bearing off shaft due to being seized shined shaft installed new seal and installed shaft, installed bearing and housing installed sensor and bracket and tightened hardware


Part Number	
03M7193	

Description BOLT

Quantity 1.00 **List Price** 1.02 Net Price 1.02

Extended Price Taxed Ind \$1.02







Invoice To Account No:		SERVICE INVOIC				DICE
Internal Used Stock No	o. 560826 (Sold)	1	nvoice N	umber:	24	50917
			Invoic	e Date:	7/1	15/2020
			Lo	ocation:		30
		Wor	k Order N	lumber:	•	422060
Bus Phone:			Paymer	nt Type:	A	Account
Prv Phone:	Mob Phone:			Page:		3 of 44
Deliver To:		·			*****	
Internal Used Stock No PLATTE VALLEY EQUIP	PMENT CÒ	Make	/Model:	JOHN DEERE PDRV/2WD/650	X85R38DLS/75	50X65F
2221 COUNTY ROAD Q PO BOX 1060	l	Meter	r:	1409		
FREMONT NE 68025		Seria	Number:	1H0S690SAG07	85341	
Bus Phone:		Eq ID):	SAG0785341		
Prv Phone:	Mob Phone:	Fleet	No:			
//S690 CMBS155 Intern	nal					
14M7296	10 MM Flanged Nut	1.00	1.10	1.10	\$1.10	N
AH231479	BEARING WI	1.00	150.19	150.19	\$150.19	N
H223849	RING	1.00	4.50	4.50	\$4.50	Ν

OL&M: \$0.00

Misc: \$0.00

//S690 CMBS13 Internal

Labor: \$225.00

COMPLAINT:

05 Feeder house floor, R&R (both pieces)

CORRECTION:

Feeder house floor, R&R
Removed feed floor seal
removed lock arm and bar for feed floor
removed reverser cooler hardware swung cooler to side
removed fore aft cylinder hoses and reverser hoses
removed reverser cable from floor
removed hardware holding floor to feeder house and dropped floor out the bottom
installed new floor into feeder house
installed in reverse order

Parts: \$156.81


Part Number AXE29353	<u>Description</u> FLOOR		Quantity 1.00	<u>List Price</u> 1,389.94	Net Price 1,389.94	Extended Price \$1,389.94	Taxed Ind N
H173904	SEAL		1.00	73.56	73.56	\$73.56	N
Labor: \$750.00	Parts: \$1,463.50	OL&M: \$0.00	Misc:	\$0.00	Sub-To	otal: \$2,213.5	0

//S690 CMBS11 B Internal

COMPLAINT:

Sub-Total: \$381.81







Invoice To Account No:

SERVICE INVOICE

Internal Used Stock No	. 560826 (Sold)	Invoice Number:	2450917
		Invoice Date:	7/15/2020
		Location:	30
		Work Order Number:	422060
		Payment Type:	Account
Bus Phone:			
Prv Phone:	Mob Phone:	Page:	4 of 44

Deliver To:

Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO

2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Mob Phone:

Make/Model:

JOHN DEERE

PDRV/2WD/650X85R38DLS/750X65R

Meter:

140

Serial Number: 1H0S690SAG0785341

Eq ID: S

SAG0785341

Fleet No:

//S690 CMBS11 B Internal

06 Feeder house front feed plate, R&R (w/ Contour Master)

CORRECTION:

Feeder house front feed plate, R&R
Removed bolts holding plate to combine
discarded feed plate and seal
assembled new plate and seal
installed into combine and tightened hardware
applied sealant to corners
operated for function of door opening and closing correctly


Labor: \$525.00	Parts: \$636.54	OL&M: \$0.00	Misc: \$	0.00	Sub-To	otal: \$1,161.5	4
H130057	PIN FASTEN		1.00	92.77	92.77	\$92.77	N
AH227675	HINGE		1.00	213.88	213.88	\$213.88	N
AH156157	PLATE		1.00	324.17	324.17	\$324.17	N
Part Number 03M7195	Description 10 X 45 CARR. GR 8.	8	<u>Quantity</u> 4.00	List Price 1.43	Net Price 1.43	\$5.72	Taxed Ind N

//S690 CMBS291 Internal

COMPLAINT:

07 Shoe auger front bearing, R&R (per auger) 2







Invoice To Account No:

SERVICE INVOICE

PDRV/2WD/650X85R38DLS/750X65F

Internal Used	Stock No. 560826 (Sold)	Invoice Number:	2450917
		Invoice Date:	7/15/2020
		Location:	30
·		Work Order Number:	422060
		Payment Type:	Account
Bus Phone:			
Prv Phone:	Mob Phone:	Page:	5 of 44

Deliver To:

Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO

2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Meter:

1409

Make/Model:

Serial Number: 1H0S690SAG0785341

JOHN DEERE

Eq ID:

SAG0785341

Fleet No:

//S690 CMBS291 Internal

Shoe auger bearings, R&R (per auger) 2 Removed separator shields removed mounting hardware for augers removed augers removed roll pin for bevel gear and removed gear removed locking collar shined shaft and removed bearing and housing replaced bearing and flanges and reinstalled onto shaft set lock collar and tightened set screw installed bevel gear and installed roll pin installed auger into combine did same procedure to other auger

Part Number AXE39453	<u>Description</u> BEARING		Quantity 2.00	List Price 32.70	Net Price 32.70	Extended Price \$65.40	Taxed Ind N
H103264	PRESSED FL		4.00	2.22	2.22	\$8.88	N
Labor: \$300.00	Parts: \$74.28	OL&M: \$0.00	Misc: \$	0.00	Sub-To	tal: \$374.28	

//S690 CMBS68 Internal


COMPLAINT:

08 Final drive (ring & pinion), R&R (per side) Reseal shaft on LH side and pinion end cap, install missing spacer hardware

Mob Phone:

Reseal pinion end cap on RH side, install missing spacer hardware







Invoice To Account No:

SERVICE INVOICE

Internal Used	Stock No. 560826 (Sold)	Invoice Number:	2450917
		Invoice Date:	7/15/2020
		Location:	30
	•	Work Order Number:	422060
		Payment Type:	Account
Bus Phone:			
Prv Phone:	Mob Phone:	Page:	6 of 44

Deliver To:

Internal Used Stock No. 560826 (Sold)
PLATTE VALLEY EQUIPMENT CO

2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Mob Phone:

Make/Model:

JOHN DEERE

PDRV/2WD/650X85R38DLS/750X65F

Meter:

1409

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

//S690 CMBS68 Internal

Final drive (ring & pinion), R&R (per side)

Raised combine

removed outer dual hardware and removed dual

removed inner dual spacer and hardware and removed inner dual

removed pinion end cap

measured shims and cleaned up mating surfaces, cleaned out bolt holes for end cap applied blue form in place gasket to surfaces and installed end cap and new shims

applied loctite to bolts and torqued bolts

installed inner dual and spacer applied never seize to bolts and installed and torqued to spec

installed outer dual applied never seize to bolts and installed and torqued


Labor: \$682.50	Parts: \$146.95 OL&M: \$0.00	Misc: \$	\$0.00	Sub-To	otal: \$829.45	
KENSOL	BRAKE/METAL CLE	2.00	3.60	3.60	\$7.20	N
PM38657	Sealant - HIGH FLEX FORM-IN-PLACE GASKET	1.00	20.83	20.83	\$20.83	, N
H163745	SHIM	1.00	3.68	3.68	\$3.68	N
H163561	SPACER	4.00	15.62	15.62	\$62.48	N
H161543	SHIM	1.00	3.80	3.80	\$3.80	N
H161542	SHIM	1.00	5.91	5.91	\$5.91	N
H161541	SHIM	1.00	8.45	8.45	\$8.45	N
<u>Part Number</u> 19M7889	<u>Description</u> CAP SCREW	Quantity 4.00	List Price 8.65	Net Price 8.65	Extended Price \$34.60	Taxed Ind N

//S690 CMBS2 Internal

COMPLAINT:

09 Feeder house conveyor chain, R&R replace upper shaft sprockets and bearings replace upper chain guide support piece and guides







Invoice To Account No:

SERVICE INVOICE

Internal Used St	ock No. 560826 (Sold)	Invoice Number:	2450917
		Invoice Date:	7/15/2020
		Location:	30
		Work Order Number:	422060
		Payment Type:	Account
Bus Phone:			
Prv Phone:	Mob Phone:	Page:	7 of 44

Deliver To:

Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO 2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Mob Phone:

Make/Model:

JOHN DEERE

PDRV/2WD/650X85R38DLS/750X65F

Meter:

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

//S690 CMBS2 Internal

CORRECTION:

lowered feeder house

removed face plate black shielding

removed conveyor chain connecting links and removed chain

removed top cover seal

removed set screws for sprockets and air hammered sprockets to middle of shaft

removed bearing housing hardware and pulled shaft and bearings out of feeder house

removed bearings

removed sprockets

cleaned shaft installed new sprockets

couldnt remove bearings from housings got new bearing housings and installed bearings

installed shaft into feederhouse and torqued bearing housing hardware to spec

installed new keys to shaft and slid sprockets over keys

removed hardware for chain guides, removed chain guide support bracket and discarded

installed new bracket and installed new chain guide and hardware

installed new conveyor chain and installed connecting links


spun chain through several times to center sprockets, installed new set screws and torqued to spec

installed face plate shield

installed top cover seal

<u>Part Number</u> 11M7032	Description COTTER PIN	Quantity 1.00	List Price 0.44	Net Price 0.44	Extended Price \$0.44	Taxed Ind N
19M7783	10X16FL 10	4.00	0.90	0.90	\$3.60	N
24H1909	Washer	4.00	2.81	2.81	\$11.24	N
AH220541	CHAIN LINK	4.00	11.34	11.34	\$45.36	N
AXE27136	Support	1.00	211.00	211.00	\$211.00	N
AXE27247	Roller Chain	1.00	2,207.21	2,207.21	\$2,207.21	N
H147593	HOUSING	4.00	101.29	101.29	\$405.16	Ν
H156580	SET SCREW	16.00	3.05	3.05	\$48.80	N







Invoice To Account No:		SERVICE INVOICE				
Internal Used Stock N	o. 560826 (Sold)	Inv	oice Num	ber:	245	50917
		Invoice Date:		Date:	7/15/2020	
(**)			Loca			30
		1	Order Num			122060
Bus Phone:			Payment T	ype:	Α	ccount
Prv Phone:	Mob Phone:		P	age:		8 of 44
Deliver To:	3 17 19 19 19 19 19 19 19 19 19 19 19 19 19					***************************************
PLATTE VALLEY EQUI		Make/M	IOGOI.	OHN DEERE DRV/2WD/650)	X85R38DLS/75	0X65F
2221 COUNTY ROAD O	Q	Meter:	14	109		
FREMONT NE 68025		Serial N	lumber: 11	10S690SAG07	85341	
Bus Phone:		Eq ID:	SA	AG0785341		
Prv Phone:	Mob Phone:	Fleet N				
1 TO THOME.	Mod Filono.	Trectiv	····			
//S690 CMBS2 Interna H171960	ıl STRIP	4.00	22.65	22.65	\$90.60	N
H229470	Key,Woodruff .375x5.246	4.00	8.60	8.60	\$34.40	Ν
HXE123463	CHAIN SPRO	4.00	124.72	124.72	\$498.88	Ν
HXE47183	GUIDE	1.00	35.19	35.19	\$35.19	N
HXE47186	GUIDE	1.00	20.94	20.94	\$20.94	N
JD10020	BALL BEARI	1.00	38.62	38.62	\$38.62	Ν
JD9373	BALL BEARI	1.00	36.77	36.77	\$36.77	Ν

OL&M: \$0.00

Misc: \$0.00

//S690 CMBS201 Internal

Labor: \$1,650.00

COMPLAINT:

10 Service: Reverser, Change oil

CORRECTION:

Reverser, Change oil

Lowered feeder hose removed drain plug and drained oil,

installed drain plug raised feeder house and filled reverser with oil checked level and installed dip stick

Parts: \$3,688.21


_	Labor: \$150.00	Parts: \$147.00	OL&M: \$0.00	Misc: \$	0.00	Sub-To	otal: \$297.00	
	KENSOL	BRAKE/METAL CLE		2.00	3.60	3.60	\$7.20	N
	TY26408	qt HD460 full syn gear	lube	<u>Quantity</u> 5.00	27.96	27.96	\$139.80	Taxed Ind N

//S690 CMBS438 Internal

COMPLAINT:

Sub-Total: \$5,338.21







Invoice To Acco	unt No:
Internal Used	Stock

SERVICE INVOICE

No. 560826 (Sold) Invoice Number: 2450917 Invoice Date: 7/15/2020 Location: 30 Work Order Number: 422060 Payment Type: Account Bus Phone: Prv Phone: Mob Phone: Page: 9 of 44

Deliver To:

Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO 2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Make/Model:

JOHN DEERE

PDRV/2WD/650X85R38DLS/750X65F

Meter:

1409

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

//S690 CMBS438 Internal

11 Feeder house fixed drive belt, replace

CORRECTION:

Feeder house fixed drive belt, replace Loosened tensioner removed upper fixed pulley shields removed belt and installed new installed shields tensioned belt

Part Number

HXE47152

Description

V-BELT

Quantity 1.00 List Price

536.44

Net Price

Extended Price 536.44

Labor: \$150.00

Mob Phone:

OL&M: \$0.00

Misc: \$0.00

\$536.44

Parts: \$536.44

Sub-Total: \$686.44

Gen12- Internal

COMPLAINT:

reseal leaking tilt cylinder for face plate

CORRECTION:

cleaned area of leaking fitting removed hose and fitting from cylinder cleaned fitting and removed orings, installed new orings to fittings and installed to cylinder and tightened operated face plate checked for leaks

Part Number

T77613

Description

O-RING

\$0.00

Quantity 1.00 List Price 1.49

Net Price 1.49 Extended Price

Taxed Ind \$1.49

Labor: \$75.00


Parts: \$1.49

OL&M:

Misc: \$0.00

Sub-Total: \$76.49







Invoice To Account No:

SERVICE INVOICE

Internal Used Stock N	lo. 560826 (Sold)	Invoice Number:	2450917
		Invoice Date:	7/15/2020
		Location:	30
		Work Order Number:	422060
		Payment Type:	Account
Bus Phone:			
Prv Phone:	Mob Phone:	Page:	10 of 44

Deliver To:

Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO

Mob Phone:

2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Make/Model:

JOHN DEERE

PDRV/2WD/650X85R38DLS/750X65R

Meter:

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

Gen13- Internal

COMPLAINT:

Fore/Aft tilt seal on feederhouse ripped

CORRECTION:

Removed verton pads Removed hardware for seal strips removed strips and seal and discarded installed new seal and strips installed verton pads

Labor: \$150.00	Parts: \$145.42	OL&M: \$0.00	Misc: \$	0.00	Sub-To	tal: \$295.42	
HXE84786	Reinforcement		1.00	47.59	47.59	\$47.59	N
HXE84785	ISOLATOR		1.00	57.03	57.03	\$57.03	Ν
<u>Part Number</u> H219490	<u>Description</u> Reinforcement		Quantity 1.00	List Price 40.80	Net Price 40.80	Extended Price \$40.80	Taxed Ind N

Gen14- Internal


COMPLAINT:

Upper feederhouse fixed drive pulley bearings loose, replace

CORRECTION:

Removed shields loosened drive belt removed bracket and position arm for sensor removed snapring and removed pulley washed pulley removed snaprings and bearings and discarded loose bearings pressed new bearings in and installed snaprings installed in reverse order







Invoice To Account No:	SERVICE INVOICE	CE
Internal Used Stock No. 560826 (Sold)	Invoice Number: 24509 Invoice Date: 7/15/2 Location: Work Order Number: 422 Payment Type: According	2020 30 2060
Bus Phone: Prv Phone: Deliver To:	Page: 11 c	of 44
Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO 2221 COUNTY ROAD Q PO BOX 1060 FREMONT NE 68025	Make/Model: JOHN DEERE PDRV/2WD/650X85R38DLS/750X6 Meter: 1409 Serial Number: 1H0S690SAG0785341	65F

Gen14- Internal

Bus Phone: Prv Phone:

	Labor: \$450.00	Parts: \$77.69	OL&M: \$0.00	Misc: \$	0.00	Sub-To	otal: \$527.69	
_	T14931	SNAP RING		1.00	7.47	7.47	\$7.47	N
	Part Number JD10018	<u>Description</u> BEARING		Quantity 2.00	List Price 35.11	<u>Net Price</u> 35.11	Extended Price \$70.22	Taxed Ind N

Eq ID:

Fleet No:

SAG0785341

//S690 CMBS296 Internal

COMPLAINT:

15 Feed accelerator wear strips, Reverse or Replace

CORRECTION:

Feed accelerator wear strips, Reverse or Replace Removed hardware and removed worn strips and discarded installed new serrated wear strips and tightened hardware

Mob Phone:


<u>Part Number</u>	<u>Description</u>		Quantity	<u>List Price</u>	Net Price	Extended Price	<u>Taxed Ind</u>
HXE111121	Flat Wear Plate		32.00	20.54	20.54	\$657.28	N
Labor: \$300.00	Parts: \$657.28	OL&M: \$0.00	Misc: \$	0.00	Sub-To	otal: \$957.28	

//S690 CMBS219 Internal

COMPLAINT:

16 Chaffer pitman bearings, R&R both sides (w/out drive shaft bearings)







Invoice To Account No:

SERVICE INVOICE

Internal Used	Stock No. 560826 (Sold)	Invoice Number:	2450917
		Invoice Date:	7/15/2020
		Location:	30
		Work Order Number:	422060
·		Payment Type:	Account
Bus Phone:			
Prv Phone:	Mob Phone:	Page:	12 of 44

Deliver To:

Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO

2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Mob Phone:

Make/Model:

JOHN DEERE

PDRV/2WD/650X85R38DLS/750X65F

Meter:

1409

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:


//S690 CMBS219 Internal

Chaffer pitman bearings, R&R both sides
Removed belt from drive pulley
removed drive pulley
removed drive pulley
removed drive pulley hub
marked pitman drive arm bearings for reassembly and removed from shaft
removed bolts and split bearing housings, removed snaprings and pressed bearings off and pressed new on
assembled pitman arm bearings into housings and installed onto combine
assembled in reverse order and did same procedure to other side

Labor: \$450.00	Parts: \$434.14	OL&M: \$0.00	Misc: \$	50.00	Sub-To	otal: \$884.14	
T119912	WASHER		2.00	2.43	2.43	\$4.86	N
R43383	SNAP RING		4.00	12.07	12.07	\$48.28	N
AH125975	BALL BEARI		4.00	92.21	92.21	\$368.84	N
19M7843	16X35FL 10		2.00	2.62	2.62	\$5.24	N
<u>Part Number</u> 19M7804	<u>Description</u> 10X40FL 10		Quantity 4.00	List Price 1.73	Net Price 1.73	Extended Price \$6.92	Taxed Ind N

//S690 CMBS651 Internal COMPLAINT:







Invoice To Account No:

SERVICE INVOICE

Internal Used St	ock No. 560826 (Sold)	Invoice Number:	2450917
e * .		Invoice Date:	7/15/2020
		Location:	30
		Work Order Number:	422060
		Payment Type:	Account
Bus Phone:			
Prv Phone:	Mob Phone:	Page:	13 of 44

Deliver To:

Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO

2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Make/Model:

JOHN DEERE

PDRV/2WD/650X85R38DLS/750X65R

Meter:

1409

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

//S690 CMBS651 Internal

17 Service: All fluids & filters, Replace (does not include greasing)

Mob Phone:

Includes:

Engine oil & filter

Engine air filters

Engine fuel filters

Engine coolant & filters (if equipped)
Transmission oil & filters (if equipped)

Hydraulic/Hydrostat oil & Filters

Final drive oil

Cab filters

Engine gear case oil & filter

Reverser gear case oil

Primary countershaft gear case oil

Two Speed Rotor drive gear case oil


CORRECTION:

Service: All fluids & filters, Replace

Part Number A52523	<u>Description</u> Ring	Quantity 1.00	List Price 11.65	Net Price 11.65	Extended Price \$11.65	Taxed Ind N
AH128449	Hydraulic Filter Element	1.00	53.60	53.60	\$53.60	N
AN207368	HYDRAULIC	1.00	80.36	80.36	\$80.36	N
AXE12964	HYDRAULIC FI	1.00	66.72	66.72	\$66.72	N
AXE42065	FILTER ELEME	1.00	51.85	51.85	\$51.85	N
AXE42066	FILTER ELEME	1.00	95.55	95.55	\$95.55	N
DZ112918	Fuel filter Element	1.00	94.99	94.99	\$94.99	N
HXE11090	Air Filter Primary	1.00	169.75	169.75	\$169.75	N
HXE11091	FILTER	1.00	134.24	134.24	\$134.24	N



Internal Used Stock No. 560826 (Sold)





www.plattevalleyequipment.com

Invoice To Account No:

SERVICE INVOICE

Invoice Number:

2450917

		Invoi	ce Date:	7/15/2020			
	Location:			30			
		Work Order	Number:	42206			
		Payme	nt Type:	Ac	count		
Bus Phone:							
Prv Phone:	Mob Phone:		Page:	14	of 44		
Deliver To:							
Internal Used Stock No.	,	Make/Model:	JOHN DEERE				
PLATTE VALLEY EQUIP	MENT CO		PDRV/2WD/650X	(85R38DLS/750)	K65F		
2221 COUNTY ROAD Q		Meter:	1409				
PO BOX 1060 FREMONT NE 68025		Serial Number	Serial Number: 1H0S690SAG0785341				
		Eq ID:	SAG0785341				
Bus Phone:		= 10.	0AG0703341				
Prv Phone:	Mob Phone:	Fleet No:	-				


Labor: \$750.00	Parts: \$1,307.81 OL&M: \$0.00	Misc: \$	0.00	Sub-Total:	\$2,057.81	
TY26679	5g Plus-50 II Oil 15W40 CK4/SN	2.00	98.22	98.22	\$196.44	N
TY26675	2.5g Plus-50 II Oil 15W40 CK4/SN	1.00	50.67	50.67	\$50.67	Ν
TY26576	2.5g Cool-Gard II 50/50 Premix	2.00	32.21	32.21	\$64.42	Ν
RE572785	Engine Oil Filter 13.6L	1.00	52.15	52.15	\$52.15	Ν
RE539465	Fuel Filter *10M	1.00	79.48	79.48	\$79.48	Ν
RE284091	Cab Air Filter, Small, Fresh Air	1.00	56.93	56.93	\$56.93	Ν
N309233	O-RING	1.00	9.67	9.67	\$9.67	Ν
L214634	Cab filter (MUST SELL 2 PER BOX)	2.00	19.67	19.67	\$39.34	N

//S690 CMBS292 Internal

COMPLAINT:

18 Concaves, R&R, & level (set of 3)







Invoice To Account No:

SERVICE INVOICE

Internal Used Stock No	o. 560826 (Sold)	Invoice Number:	2450917
		Invoice Date:	7/15/2020
		Location:	30
		Work Order Number:	422060
		Payment Type:	Account
Bus Phone:			
Prv Phone:	Mob Phone:	Page:	15 of 44

Deliver To:

Internal Used Stock No. 560826 (Sold)
PLATTE VALLEY EQUIPMENT CO

2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Mob Phone:

Make/Model:

JOHN DEERE

PDRV/2WD/650X85R38DLS/750X65F

Meter:

1409

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

//S690 CMBS292 Internal

Concaves, R&R, & level (set of 3)

Set concaves to 0 position

removed separator covers

removed locking pins on RH side and retained

removed hardware holding concaves to z bar

removed and discarded concaves

removed wear plate on z bar and discarded installed new wear plate and hardware

installed new concaves

installed in reverse position

went through process to make sure concaves were level

went started machine and set to 0

removed cylinder lock pins and removed concave adjusting bolt

loosened jam nuts on arms went through calibration in display

spun rotor counter clockwise and tightened rear level screw over till tick was heard and backed off screw three turns

spun rotor counter clockwise and tightened front level screw over till tick was heard and backed off screw three turns

spun rotor counter clockwise and tightened rear level screw til tick was heard then backed off one half turn

spun rotor counter clockwise and tightened front level screw til tick was heard then backed off one half turn


tightened hardware

went through step 2 and adjusted leveling stops

went through and calibrated threshing clearance

<u>Part Number</u> BXE10387	Description EXT WEAR ROUND BAR CONCAVE KIT	Quantity 1.00	<u>List Price</u> 2,420.00	Net Price 2,420.00	Extended Price \$2,420.00	Taxed Ind N
H135891	LOCK NUT	6.00	1.17	1.17	\$7.02	N
H174755	BOLT	6.00	1.41	1.41	\$8.46	N
HXE110110	Z-bar Wear Plare (Extended wear)	1.00	272.06	272.06	\$272.06	N
Miscellaneous FREIGHT	<u>Description</u> FREIGHT	Quantity 1.00	<u>List Price</u> 50.00	Net Price 50.00	Extended Price \$50.00	Taxed Ind N
Labor: \$345.00	Parts: \$2,707.54 OL&M: \$0.00	Misc:	\$50.00	Sub-To	otal: \$3,102.5	4







Invoice	Tο	Account	No:

SERVICE INVOICE

Internal Used	Stock No. 560826 (Sold)	Invoice Number:	2450917
		Invoice Date:	7/15/2020
		Location:	30
		Work Order Number:	422060
		Payment Type:	Account
Bus Phone:			
Prv Phone:	Mob Phone:	Page:	16 of 44

Deliver To:

Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO 2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Mob Phone:

Make/Model:

JOHN DEERE

PDRV/2WD/650X85R38DLS/750X65R

Meter:

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

//S690 CMBS949 Internal

COMPLAINT:

19 Shoe auger rear bearings/blocks, R&R (per auger)

CORRECTION:

Shoe auger rear bearings/blocks, R&R

Labor: \$150.00	Parts: \$120.80	OL&M: \$0.00	Misc: \$	0.00	Sub-To	otal: \$270.80	
JD8554	1 inch Locking Collar		2.00	5.97	5.97	\$11.94	N
AH163056	<u>Description</u> Bearing with housing		Quantity 2.00	<u>List Price</u> 54.43	Net Price 54.43	Extended Price \$108.86	Taxed Ind N

Gen20- Internal

COMPLAINT:


Grain loss sensor by rotor not operating, diagnose and replace

CORRECTION:

Removed wiring from sensor and mounting hardware discarded bad sensor and installed new tested sensor for operation

Labor: \$150.00	Parts: \$119.55	OL&M: \$0.00	Misc: \$	0.00	Sub-To	otal: \$269.55	
AXE55969	SENSOR		1.00	116.87	116.87	\$116.87	N
21H1492	SCREW		4.00	0.38	0.38	\$1.52	N
Part Number 12M7060	<u>Description</u> WASHER		Quantity 4.00	<u>List Price</u> 0.29	Net Price 0.29	Extended Price \$1.16	Taxed Ind N







Invoice To Account No:

SERVICE INVOICE

Internal Used	Stock No. 560826 (Sold)	Invoice Number:	2450917
		Invoice Date:	7/15/2020
		Location:	30
V' .		Work Order Number:	422060
		Payment Type:	Account
Bus Phone:			
Prv Phone:	Mob Phone:	Page:	17 of 44

Deliver To:

Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO

2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Mob Phone:

Make/Model:

JOHN DEERE

PDRV/2WD/650X85R38DLS/750X65F

Meter:

1409

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

Gen21- Internal

COMPLAINT:

shaker pan plastic ribbed pieces worn through, replace

CORRECTION:

while had chaffer seive extended precleaner out from mounting bolts for shaker pan removed shaker pan from combine removed strip holding shaker pan plastic ribbed pieces in and removed ribbed pieces washed off shaker pan installed new ribbed pieces installed new strip and hardware inspected seals soaped seals and installed shaker pan installed mounting hardware and tightened

 Labor: \$900.00	Parts: \$262.80	OL&M: \$0.00	Misc: \$	0.00	Sub-To	otal: \$1,162.8	0
HXE96702	Retainer		1.00	64.80	64.80	\$64.80	N
HXE83661	Return Pan		2.00	95.08	95.08	\$190.16	Ν
<u>Part Number</u> 19M7868	Description 8X30FL 10		Quantity 8.00	<u>List Price</u> 0.98	Net Price 0.98	Extended Price \$7.84	Taxed Ind N

//S690 CMBS328 Internal


COMPLAINT:

22 Unloading auger drive chain, R&R

CORRECTION:

Unloading auger drive chain, R&R Loosened tension on chain removed worn chain and discarded installed new chain and routed tenioned chain







Invoice To Account No:

SERVICE INVOICE

Internal Used	Stock No. 560826 (Sold)	Invoice Number:	2450917
•		Invoice Date:	7/15/2020
		Location:	30
		Work Order Number:	422060
		Payment Type:	Account
Bus Phone:			
Prv Phone:	Mob Phone:	Page:	18 of 44

Deliver To:

Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO

Mob Phone:

2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Make/Model:

JOHN DEERE

PDRV/2WD/650X85R38DLS/750X65R

Meter:

1409

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

//S690 CMBS328 Internal

Labor: \$90.00	Parts: \$326.23	OL&M:	\$0.00	Misc: \$	\$0.00	Sub-Tot	al: \$416.23	
AXE79735	ROLLER CHA			1.00	231.90	231.90	\$231.90	N
Part Number AXE16264	Description CHAIN SPRO			Quantity 1.00	List Price 94.33	Net Price 94.33	Extended Price \$94.33	Taxed Ind N

//S690 CMBS485 Internal

COMPLAINT:

23 Discharge beater drive belt, R&R

CORRECTION:

Discharge beater drive belt, R&R Removed chopper belts loosened tensioner for beater belt removed pulley cover and clamps for hoses removed belt and installed new installed in reverse order


Part Number AH236689	Description V-BELT			Quantity 1.00	List Price 238.94	Net Price 238.94	\$238.94	Taxed Ind N
 Labor: \$112.50	Parts: \$238.94	OL&M:	\$0.00	Misc: \$	0.00	Sub-To	tal: \$351.44	

//S690 CMBS352 Internal

COMPLAINT:

24 Discharge beater wear strips, Reverse or Replace Note: Update to 2-piece design, drill additional holes







Invoice To Account No:

SERVICE INVOICE

Internal Used Stock N	o. 560826 (Sold)	Invoice Number:	2450917
		Invoice Date:	7/15/2020
**		Location:	30
		Work Order Number:	422060
		Payment Type:	Account
Bus Phone:			
Prv Phone:	Mob Phone:	Page:	19 of 44
Deliver To:		J	

OL&M: \$0.00

Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO

2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Mob Phone:

Make/Model:

JOHN DEERE

PDRV/2WD/650X85R38DLS/750X65R

Sub-Total: \$300.00

Meter:

1409

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

Misc: \$0.00

//S690 CMBS352 Internal

CORRECTION:

Discharge beater wear strips, Reverse or Replace Removed hardware for each strip, reversed strips to where they would ware down evenly installed hardware and tightened

Parts: \$0.00

Labor: \$300.00

//S690 CMBS284 Internal COMPLAINT:


25 Discharge beater grate, replace missing and broken nails

CORRECTION:

Discharge beater grate, replace missing and broken nails
Removed mounting hardware
removed grate from combine
removed strip holding nails in grate
cut out and removed broken nails
installed new nails
installed holding strip
lifted grate into combine and installed mounting hardware, tightened hardware

Part Number 14M7299	Description 12MM FL NUT	Quantity 4.00	<u>List Price</u> 1.48	Net Price 1.48	Extended Price \$5.92	Taxed Ind N
19M7813	12X45FL 10	4.00	2.38	2.38	\$9.52	N
H146457	NUT	4.00	1.79	1.79	\$7.16	N
H229469	NAIL	22.00	6.91	6.91	\$152.02	N







Invoice	т_	A	NIA.
HIVUICE	10.	Account	INU.

SERVICE INVOICE

Internal Used	Stock No. 560826 (Sold)	Invoice Number:	2450917
		Invoice Date:	7/15/2020
** *		Location:	30
		Work Order Number:	422060
1.		Payment Type:	Account
Bus Phone:			
Prv Phone:	Mob Phone:	Page:	20 of 44

OL&M: \$0.00

Deliver To:

Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO 2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Mob Phone:

Make/Model:

JOHN DEERE

PDRV/2WD/650X85R38DLS/750X65R

Meter:

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

//S690 CMBS284 Internal

Labor: \$487.50

12704

CUT-OFF WHEELS

Parts: \$178.66

1.00

Misc: \$0.00

4.04

4.04

\$4.04

Sub-Total: \$666.16

Ν

Gen26- Internal COMPLAINT:

Chopper jackshaft drivebelt has holes through backing

CORRECTION:

chopper drive belt had holes and cracks raised chopper released tension on chopper drive belts removed outer drive belt removed inner drive belt and discarded installed new belt installed outer belt tensioned belts lowered chopper


	Part Number 14M7275	Description 12 mm Metric Hex Nut, Gd	10		Quantity 4.00	<u>List Price</u> 0.94	Net Price 0.94	Extended Price \$3.76	Taxed Ind N
•	HXE124869	V-BELT			1.00	457.81	457.81	\$457.81	N
	Labor: \$300.00	Parts: \$461.57	OL&M:	\$0.00	Misc:	\$0.00	Sub-Tot	al: \$761.57	

//S690 CMBS498 Internal

COMPLAINT:

27 Straw chopper outlet housing (Lobster tail), Replace







Invoi	ce To	Acco	unt	No.
III V V II	FC 10	$\neg \circ \circ \circ$	uiii	INO.

SERVICE INVOICE

Internal Used Stock I	No. 560826 (Sold)	Invoice Number:	2450917
		Invoice Date:	7/15/2020
		Location:	30
-		Work Order Number:	422060
		Payment Type:	Account
Bus Phone:			
Prv Phone:	Mob Phone:	Page:	21 of 44

Deliver To:

Internal Used Stock No. 560826 (Sold)

PLATTE VALLEY EQUIPMENT CO

2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Make/Model:

JOHN DEERE

PDRV/2WD/650X85R38DLS/750X65R

Meter:

1409

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

//S690 CMBS498 Internal

Straw chopper outlet housing (Lobster tail), Replace Removed hardware and removed lobster tail swapped brackets and wear strip to new housing installed housing and installed and tightened hardware

Mob Phone:

Labor: \$375.00	Parts: \$932.85	OL&M: \$0.00	Misc: \$	0.00	Sub-To	otal: \$1,307.8	5
H137328	LOCK NUT		13.00	0.88	0.88	\$11.44	N
AXE20855	HOUSING		1.00	910.64	910.64	\$910.64	N
19M7866	8X20FL 10		8.00	0.94	0.94	\$7.52	Ν
<u>Part Number</u> 03M7184	Description 8 X 20 CARBOLT		Quantity 5.00	<u>List Price</u> 0.65	Net Price 0.65	Extended Price \$3.25	Taxed Ind N

Gen28- Internal

COMPLAINT:

install quick locks for spreader shield

CORRECTION:

Installed quick locks on spreader shield


Part N M725		Description QUICK				Quantity 7.00	List Price 1.95	Net Price 1.95	Extended Price \$13.65	Taxed Ind N
Labo	or: \$37.50	Parts:	\$13.65	OL&M:	\$0.00	Misc:	\$0.00	Sub-Tot	tal: \$51.15	

//S690 CMBS39 Internal

COMPLAINT:

29 Straw chopper hammers, Replace (Includes blowing out loop style)







Invoice To Account No:

SERVICE INVOICE

Internal Used	Stock No. 560826 (Sold)	Invoice Number:	2450917
		Invoice Date:	7/15/2020
		Location:	30
		Work Order Number:	422060
		Payment Type:	Account
Bus Phone:			
Prv Phone:	Mob Phone:	Page:	22 of 44

Deliver To:

Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO

2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Meter:

Make/Model:

PDRV/2WD/650X85R38DLS/750X65F

1409

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

JOHN DEERE

Fleet No:

//S690 CMBS39 Internal

CORRECTION:

Straw chopper hammers, Replace (Includes blowing out loop style)

Removed lobster tail

removed and discarded all hammer knives and paddles and discarded all hardware

Mob Phone:

installed new knives and paddles with new bushings and hardware

 Labor: \$352.50	Parts: \$2,460.60 OL&M: \$0.00	Misc: S	\$148.00	Sub-To	otal: \$2,961.1	0
Miscellaneous FREIGHT	<u>Description</u> FREIGHT	Quantity 1.00	<u>List Price</u> 148.00	<u>Net Price</u> 148.00	Extended Price \$148.00	Taxed Ind N
Z66313	WASHER	16.00	1.38	1.38	\$22.08	N
KXE10255	Kit-Straw Chop Wing Blade 4-LH & 4-RH	6.00	191.81	191.81	\$1,150.86	Ν
HXE59496	BUSHING	44.00	8.29	8.29	\$364.76	N
HXE15909	SPACER	44.00	9.74	9.74	\$428.56	Ν
HXE13967	BUSHING	16.00	12.30	12.30	\$196.80	N
HXE119246	Cap Screw	30.00	2.52	2.52	\$75.60	Ν
HXE118760	M10 LOCK NUT	30.00	1.14	1.14	\$34.20	N
AH225940	BLADE	Quantity 1.00	<u>List Price</u> 187.74	<u>Net Price</u> 187.74	Extended Price \$187.74	<u>Taxed Ind</u> N

//S690 CMBS140 Internal


COMPLAINT:

30 Straw chopper stationary knives, Reverse or Replace

CORRECTION:

Straw chopper stationary knives, Reverse or Replace







Invoice To Account No:

SERVICE INVOICE

Internal Used	Stock No. 560826 (Sold)	Invoice Number:	2450917
		Invoice Date:	7/15/2020
		Location:	30
		Work Order Number:	422060
		Payment Type:	Account
Bus Phone:			
Prv Phone:	Mob Phone:	Page:	23 of 44

Deliver To:

Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO

2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Mob Phone:

Make/Model:

JOHN DEERE

PDRV/2WD/650X85R38DLS/750X65R

Meter:

1409

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

//S690 CMBS140 Internal

_	Labor: \$150.00	Parts: \$347.61	OL&M: \$0.00	Misc: \$	50.00	Sub-To	otal: \$497.61	
	H215004	BLADE		39.00	8.38	8.38	\$326.82	N
	.14M7296	10 MM Flanged Nut		9.00	1.10	1.10	\$9.90	N
	Part Number 03M7375	Description 10MM X 30MM		<u>Quantity</u> 9.00	<u>List Price</u> 1.21	Net Price 1.21	Extended Price \$10.89	Taxed Ind N

Gen31- Internal

COMPLAINT:

Repair wiring loom on LH side by switches

CORRECTION:

Got wiring loom , wrapped wires and taped over loom


	Labor: \$75.00	Parts: \$4.29	OL&M: \$0.00		\$0.00	Sub-To		
ALIOO E E TO A E O MO O O N	AH89557 TY26189	CLIP 5/8" CONDUIT/FOOT		2.00 1.00	1.53 1.23	1.53 1.23	\$3.06 \$1.23	N N

Gen32- Internal

COMPLAINT:

Install covers onto front chaffer







Invoice	To A	ccount	No:
---------	------	--------	-----

SERVICE INVOICE

Internal Used Stock	No. 560826 (Sold)	Invoice Number:	2450917
		Invoice Date:	7/15/2020
7		Location:	30
		Work Order Number:	422060
*		Payment Type:	Account
Bus Phone:			
Prv Phone:	Mob Phone:	Page:	24 of 44

Deliver To:

Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO

2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Mob Phone:

Make/Model: JOHN DEERE

PDRV/2WD/650X85R38DLS/750X65F

Meter:

1409

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

Gen32- Internal

Raised chopper removed wiring from grain loss sensors and chaffer actuator wirng removed back piece of chaffer frame removed chaffer removed sieve wiring and sieve removed hardware installed 4 pre cleaner covers

installed in reverse order

Labor: \$450.00	Parts: \$319.18	OL&M: \$0.00	Misc: \$	60.00	Sub-To	tal: \$769.18	
HXE112557	Cover		2.00	84.18	84.18	\$168.36	Ν
HXE108167	Cover		2.00	72.64	72.64	\$145.28	N
24M7298	WASHER		4.00	0.65	0.65	\$2.60	N
<u>Part Number</u> 19M7868	Description 8X30FL 10		Quantity 3.00	<u>List Price</u> 0.98	Net Price 0.98	Extended Price \$2.94	Taxed Ind N

Gen33- Internal

COMPLAINT:

Install missing spreader shroud, install missing hardware

CORRECTION:

Removed worn carriage bolts on LH shroud and installed new hardware and tightened installed missing shroud and installed hardware and tightened

Part Number 14M7298	<u>Description</u> 8MM FL NUT	Quantity 8.00	<u>List Price</u> 0.79	Net Price 0.79	Extended Price \$6.32	Taxed Ind N
H218025	BOLT	8.00	2.71	2.71	\$21.68	Ν
H225020	SHROUD	1.00	71.29	71.29	\$71.29	N




CORRECTION:

Part Number H137328

Removed bolts and nuts and installed correct hardware

Description LOCK NUT





www.plattevalleyequipment.com

voice To Account No:					SERVICE INVOICE				
Internal Used Stock No. 5	60826 (Sold)				Invoice Nun	nber:	24	2450917	
					Invoice		7.	/15/2020	
				1		ation:		30	
. t - [√]				Y	ork Order Nur			422060	
Ruo Phono:					Payment	Type:		Account	
Bus Phone: Prv Phone:	Mob Phone:				F	Page:		25 of 44	
Deliver To:				l			.		
Internal Used Stock No. 5	560826 (Sold)			Ma	ke/Model: J	OHN DEERE	· · · · · · · · · · · · · · · · · · ·		
PLATTE VALLEY EQUIPM				""		DRV/2WD/650	X85R38DLS/7	750X65F	
2221 COUNTY ROAD Q				Me	ter: 1	409			
PO BOX 1060 FREMONT NE 68025				l se	rial Number: 1	H0S690SAG0	785341		
PREMIONI NE 08025							700041		
Bus Phone:				Eq	ID: S	AG0785341			
Prv Phone:	Mob Phone:			Fle	et No:				
Labor: \$75.00 Gen34- Internal COMPLAINT: Replace worn spreader blace CORRECTION: Removed spreader pans removed hardware for spreader installed new wings an tight installed spreader pans	ader wings and removed wir	OL&M:		1.00 Misc:	\$0.00	71.94 Sub-To	\$71.94 tal: \$246.23		
Part Number	<u>Description</u> DEFLECTOR			Quantity 12.00	<u>List Price</u> 9.40	Net Price 9.40	Extended Price \$112.80	Taxed Inc	
H214211	PADDLE			1.00	603.03	603.03	\$603.03	1	
KXE10538	FADDLE								

Quantity 2.00 List Price 0.88 Net Price 0.88 Extended Price Taxed Ind \$1.76 N



//S690 CMBS922 Internal

37 Safety shield, Replace (per shield) install missing shoe drive shield


Description 8MM FL NUT

COMPLAINT:

CORRECTION: Safety shield, Replace Installed shoe drive shield

Part Number

14M7298





www.plattevalleyequipment.com

	Invoice To Account No:					SERVICE INVOICE				
Internal Used Stock No. 560826 (Sold)					Invoice N	umber:	24	50917		
				 	Invoic	e Date:	7/	15/2020		
t de la companya de l					Lo	ocation:		30		
					ork Order N			422060		
					Paymer	nt Type:		Account		
Bus Phone:										
Prv Phone:	Mob Phone:					Page:		26 of 44		
eliver To:								va		
Internal Used Stock No.				Ma	ke/Model:	JOHN DEERE				
PLATTE VALLEY EQUIPM	MENT CO					PDRV/2WD/650	X85R38DLS//	50X65F		
2221 COUNTY ROAD Q PO BOX 1060				Me	ter:	1409				
FREMONT NE 68025				Se	rial Number:	1H0S690SAG07	785341			
,				Fa	ID:	SAG0785341				
Bus Phone:	A A a la Dala a a a a					3,133,3331,				
Prv Phone:	Mob Phone:				et No:					
Labor: \$75.00	Parts: \$6.56	OL&M:	\$0.00	Misc:	\$0.00	Sub-Tot	tal: \$81.56	 		
I/S690 CMBS836 International I	l pivot, Repair (weld hard was	sher 24M7090	on size of pivo	t bolt)						
COMPLAINT: 36 Straw chopper tailboard CORRECTION: Crack was on replaceable removed hardware and ren installed new bracket insta	d pivot, Repair (weld hard was bracket for lobster tail noved bracket lled hardware and tightened	sher 24M7090	on size of pivo					Town of the same		
COMPLAINT: 36 Straw chopper tailboard CORRECTION: Crack was on replaceable removed hardware and ren	d pivot, Repair (weld hard was bracket for lobster tail noved bracket	sher 24M7090	on size of pivo	et bolt) Quantity 1.00	<u>List Price</u> 53.74		Extended Price \$53.74	Taxed Ind		
COMPLAINT: 36 Straw chopper tailboard CORRECTION: Crack was on replaceable removed hardware and ren nstalled new bracket insta	I pivot, Repair (weld hard was bracket for lobster tail noved bracket lled hardware and tightened Description	sher 24M7090	on size of pivo	Quantity		53.74				

Net Price 0.79

List Price 0.79


Quantity

1.00

Extended Price Taxed Ind

\$0.79







Sub-Total: \$404.35

www.plattevalleyequipment.com

Invoice To Account No: SERVICE INV					CE INVO	ICE	
Internal Used Stock N	No. 560826 (Sold)	Inv	oice Nu	mber:		0917	
			Invoice		7/1	5/2020	
			Location:			30	
			Order Nu		422060 Account		
Bus Phone:			Payment	Type:	A	CCOUNT	
Prv Phone:	Mob Phone:			Page:	2	7 of 44	
Deliver To:		the state of the s					
Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO		Make/M	Make/Model: JOHN DEERE PDRV/2WD/650X85R38DLS.			0X65F	
2221 COUNTY ROAD	Q	Meter:	Meter: 1409			-	
PO BOX 1060 FREMONT NE 68025		Serial N	Serial Number: 1H0S690SAG07				
Bus Phone:		Eq ID:	;	SAG0785341			
Prv Phone:	Mob Phone:	Fleet No	D:	an Panaha wakawa wa Alice at a San a San			
//S690 CMBS922 Inte	ernal						
19M7868	8X30FL 10	1.00	0.98	0.98	\$0.98	Ν	
28H1511	WASHER	1.00	0.62	0.62	\$0.62	Ν	
AH167973	Latch Kit	1.00	36.96	36.96	\$36.96	Ν	
AXE58228	Shield	1.00	290.00	290.00	\$290.00	Ν	

OL&M: \$0.00

Misc: \$0.00

Gen38- Internal

Labor: \$75.00

COMPLAINT:

replace broken cab wall connector panel


CORRECTION:

Disconnected all connectors removed clamps and hardware holding panel to cab had to cut and break bulk head connector nuts due to being stuck to connector super glued new panel hole knockout so piece doesnt break or fall out installed in reverse order

Parts: \$329.35

	Part Number 19M7863	Description SCREW	Quantity 12.00	List Price 0.79	Net Price 0.79	Extended Price \$9.48	Taxed Ind N
	57M8035	NUT	2.00	4.92	4.92	\$9.84	Ν
	57M8428	NUT	1.00	4.72	4.72	\$4.72	N
•	L203818	Seal	1.00	16.97	16.97	\$16.97	N
	L210494	PLATE	1.00	38.31	38.31	\$38.31	Ν







Invo	ce	То	Acc	ount	No:

SERVICE INVOICE

Internal Used	Stock No. 560826 (Sold)	Invoice Number:	2450917
		Invoice Date:	7/15/2020
		Location:	30
		Work Order Number:	422060
		Payment Type:	Account
Bus Phone:			
Prv Phone:	Mob Phone:	Page:	28 of 44

Deliver To:

Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO

2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Mob Phone:

Make/Model:

JOHN DEERE

PDRV/2WD/650X85R38DLS/750X65F

Meter:

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

Gen38- Internal

PM37391

Adhesive - GEL, SUPER GLUE (.07 OZ)

2.00

2.31

2.31

\$4.62

Ν

Labor: \$300.00

Parts: \$83.94

OL&M: \$0.00

Misc: \$0.00

Sub-Total: \$383.94

//S690 CMBS262 Internal

COMPLAINT:

39 Chaffer & shoe auger drive belt, R&R

CORRECTION:

Chaffer & shoe auger drive belt, R&R Removed shields released tension on belt removed shield bracket to remove front countershaft belt removed shoe drive belt and installed new belt reinstalled in reverse order and tightened belts


<u>Part Number</u> HXE102288	<u>Description</u> V-Belt		Quantity 1.00	<u>List Price</u> 589.35	Net Price 589.35	Extended Price \$589.35	<u>Taxed Ind</u> N
Labor: \$225.00	Parts: \$589.35	OL&M: \$0.00	Misc: \$	\$0.00	Sub-To	otal: \$814.35	

//S690 CMBS389 Internal

COMPLAINT:

40 Tailings elevator upper & lower drive chains, Replace







Invoice To Account No:

SERVICE INVOICE

Internal Used Stock	: No. 560826 (Sold)	Invoice Number:	2450917
		Invoice Date:	7/15/2020
-		Location:	30
		Work Order Number:	422060
* * *		Payment Type:	Account
Bus Phone:			
Prv Phone:	Mob Phone:	Page:	29 of 44

Deliver To:

Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO

PLATTE VALLET EQUIPMEN

2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Mob Phone:

Make/Model:

JOHN DEERE

PDRV/2WD/650X85R38DLS/750X65R

Meter:

1400

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

//S690 CMBS389 Internal

Tailings elevator upper & lower drive chains, Replace Removed shields loosened tensioner removed drive chain removed idler sprockets and installed new installed new chain installed shields tensioned chain

Labor: \$225.00	Parts: \$230.91	OL&M: \$0.00	Misc: S	\$0.00	Sub-To	otal: \$455.91	
H216427	Hex Spacer		1.00	10.41	10.41	\$10.41	N
H114395	SPACER		1.00	4.12	4.12	\$4.12	N
AXE54619	ROLLER CHA		1.00	151.78	151.78	\$151.78	N
Part Number AXE23133	<u>Description</u> IDLER SPRO		Quantity 2.00	List Price 32.30	Net Price 32.30	Extended Price \$64.60	Taxed Ind N

//S690 CMBS452 Internal


COMPLAINT:

41 Tailings upper auger bearing, R&R, Replace wood block (if shaft is worn, add 3/8" pipe nipples for spacers to allow bearing/lock collar new shaft area)

CORRECTION:

Tailings upper auger bearing, R&R, Replace wood block
Removed shield on LH side that covers hoses running the length of combine
cleaned debris to get to bearing
removed lock collar and removed mounting hardware
cleaned shaft and removed bearing and flanges
installed new bearing and flanges, installed hardware and tightened
installed new lock collar
installed shield







Invoice To Account No:

SERVICE INVOICE

Internal Used Stock N	lo. 560826 (Sold)	Invoice Number:	2450917
*		Invoice Date:	7/15/2020
		Location:	30
		Work Order Number:	422060
		Payment Type:	Account
Bus Phone:			
Prv Phone:	Mob Phone:	Page:	30 of 44

Deliver To:

Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO

2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Mob Phone:

Make/Model:

JOHN DEERE

PDRV/2WD/650X85R38DLS/750X65F

Meter:

1409

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

//S690 CMBS452 Internal

Labor: \$412.50	Parts: \$72.85	OL&M: \$0.00	Misc: \$	50.00	Sub-To	otal: \$485.35	
E10018	Pressed Flange		2.00	3.63	3.63	\$7.26	N
AH168161	BALL BEARI		1.00	53.77	53.77	\$53.77	N
<u>Part Number</u> AH129452	Description ECCENTRIC		<u>Quantity</u> 1.00	<u>List Price</u> 11.82	Net Price 11.82	Extended Price \$11.82	Taxed Ind N

//S690 CMBS442 Internal

COMPLAINT:


42 Clean grain elevator drive belt, Replace replace tensioner bolt

CORRECTION:

Clean grain elevator drive belt, Replace replace tensioner bolt Removed tensioner retained spring and replaced rod removed shield in grain tank and removed belt installed belt and routed installed shield and tensioned belt

Part Number 11M7030	<u>Description</u> COTTER PIN	Quantity 2.00	<u>List Price</u> 0.44	Net Price 0.44	Extended Price \$0.88	Taxed Ind N
14M7275	12 mm Metric Hex Nut, Gd 10	2.00	0.94	0.94	\$1.88	N
AXE16270	Pulley	1.00	143.41	143.41	\$143.41	Ν
HXE100088	HOOK BOLT	1.00	36.09	36.09	\$36.09	Ν







Invoice To Account No:

SERVICE INVOICE

lo. 560826 (Sold)	Invoice Number:	2450917
	Invoice Date:	7/15/2020
	Location:	30
	Work Order Number:	422060
	Payment Type:	Account
Mob Phone:	Page:	31 of 44
		Invoice Date: Location: Work Order Number: Payment Type:

Deliver To:

Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO

2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Mob Phone:

Make/Model:

JOHN DEERE

PDRV/2WD/650X85R38DLS/750X65R

Meter:

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

//S690 CMBS442 Internal

HXE20763

V-BELT

1.00 283.60 283.60

\$283.60

Ν

Labor: \$225.00

Parts: \$465.86

OL&M: \$0.00

Misc: \$0.00

Sub-Total: \$690.86

//S690 CMBS466 Internal

COMPLAINT:

43 Clean grain elevator paddle chain, R&R, Install J-hooks (H84026)

Replace auger bearings


CORRECTION:

Clean grain elevator paddle chain, R&R, Install J-hooks

got rope lowered over sprocket to bottom of elevator tied rope to links of chain pulled chain up and over sprocket and pulled through elevator and connected chain at bottom, removed cotter pins and installed j hooks adjusted chain

HXE22459	CHAIN SPRO	1.00	100.48	100.48	\$100.48	N
JD39102	BALL BEARI		21.66	21.66	\$21.66	N
JD39104	BALL BEARI	1.00	32.50	32.50	\$32.50	N







Invoice To Account No:

SERVICE INVOICE

	o. 560826 (Sold)	Invoice Number:	2450917
		Invoice Date:	7/15/2020
		Location:	30
		Work Order Number:	422060
		Payment Type:	Account
Bus Phone:			
Prv Phone:	Mob Phone:	Page:	32 of 44

Deliver To:

Internal Used Stock No. 560826 (Sold)

PLATTE VALLEY EQUIPMENT CO

2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Mob Phone:

Make/Model:

JOHN DEERE

PDRV/2WD/650X85R38DLS/750X65F

Meter:

1409

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

//S690 CMBS581 Internal

COMPLAINT:

44 Rotary screen vacuum fan countershaft bearings, Replace (Includes belts)

CORRECTION:

Rotary screen vacuum fan countershaft bearings, Replace

Removed shield

removed belts from countershaft

removed mounting hardware and removed countershaft

measured distance of pulleys on shaft and from bearings

removed pulleys, lock collars and removed bearings found shaft was worn discarded shaft installed new

installed new bearings and flanges set shaft to correct distance

installed lock collars and installed pulleys


installed countershaft into combine and installed shields

installed new drive belt and tensioned

Labor: \$487.50	Parts: \$284.53	OL&M: \$0.00	Misc: \$	0.00	Sub-To	otal: \$772.03	
HXE93567	BALL BEARI		2.00	35.53	35.53	\$71.06	N
H238867	V-BELT		1.00	31.02	31.02	\$31.02	N
H175557	SHAFT		1.00	154.13	154.13	\$154.13	N
H103264	PRESSED FL		4.00	2.22	2.22	\$8.88	N
AZ10044	ECCENTRIC		2.00	7.87	7.87	\$15.74	N
49M4100	SHAFT KEY		1.00	3.01	3.01	\$3.01	N
Part Number 26M7002	<u>Description</u> SHAFT KEY		Quantity 1.00	List Price 0.69	Net Price 0.69	Extended Price \$0.69	Taxed Ind N

//S690 CMBS343 Internal COMPLAINT:







Invoice	Τo	Account	No:
---------	----	---------	-----

SERVICE INVOICE

Internal Used Stock No. 560826 (Sold) 2450917 Invoice Number: Invoice Date: 7/15/2020 Location: 30 422060 Work Order Number: Account Payment Type: Bus Phone: 33 of 44 Mob Phone: Page: Prv Phone:

Deliver To:

Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO

2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Mob Phone:

Make/Model:

JOHN DEERE

PDRV/2WD/650X85R38DLS/750X65R

Meter:

1409

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

//S690 CMBS343 Internal

45 Rotary screen duct vacuum drive belt, Replace (HXE38073)

CORRECTION:

Rotary screen duct vacuum drive belt, Replace

Part Number HXE38073	V-BELT		1.00	21.63	21.63	\$21.63	N
Labor: \$150.00	Parts: \$21.63	OL&M: \$0.00	Misc: \$	0.00	Sub-Tot	tal: \$171.63	

//S690 CMBS594 Internal

COMPLAINT:

46 After treatment blower drive belt tensioner and idler, Replace (FT4)

CORRECTION:


Removed saftey shield released belt from tensioner removed idler and tensioner and discarded installed new idler and tensioner and routed belt and tensioned installed shield

	Labor: \$75.00	Parts: \$270.55	OL&M:	\$0.00	Misc:	\$0.00	Sub-Tot	al: \$345.55	
•	AXE64513	Belt Tensioner			1.00	158.05	158.05	\$158.05	N
	Part Number AXE37647	Description Idler			<u>Quantity</u> 1.00	<u>List Price</u> 112.50	<u>Net Price</u> 112.50	\$112.50	Taxed Ind N

//S690 CMBS573 Internal

COMPLAINT:







Invoice To Account No:

SERVICE INVOICE

Deliver To:			
Bus Phone: Prv Phone:	Mob Phone:	Page:	34 of 44
		Payment Type:	Account
		Work Order Number:	422060
* *		Location:	30
Ŧ .		Invoice Date:	7/15/2020
Internal Used Stock I	No. 560826 (Sold)	Invoice Number:	2450917

Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO 2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Mob Phone:

Make/Model:

JOHN DEERE

PDRV/2WD/650X85R38DLS/750X65R

Meter:

1409

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

//S690 CMBS573 Internal

48 Grain tank full sensor, Replace

CORRECTION:

Grain tank full sensor, Replace disconnected wiring from sensor Removed hardware and bracket and sensor installed new sensor to bracket and installed sensor and bracket to bin extension and tightened hardware

Labor: \$37.50	Parts: \$44.38 OL&M: \$0.00		Misc: \$0.00		Sub-Total: \$81.88		
AH121475	SENSOR		1.00	43.67	43.67	\$43.67	N
19M7862	6 X 20MM Hex Flange	6 X 20MM Hex Flange Screw 10.9	1.00	0.11	0.11	\$0.11	N
<u>Part Number</u> 14M7397	<u>Description</u> LOCK NUT		Quantity 1.00	<u>List Price</u> 0.60	Net Price 0.60	Extended Price \$0.60	Taxed Ind N

//S690 CMBS206 Internal

COMPLAINT:

49 Clean grain bin loading auger and housing, R&R

CORRECTION:

Clean grain bin loading auger, R&R Removed clean grain upper housing shield removed hardware and plate on LH side removed hardware and spacer on RH side removed cotter key and pin for lift assist arm got forklift and lifted auger and tube out of grain tank swapped brackets on tubes for auger to new housing with new hardware installed new auger into tube, installed new bearing to end of auger installed auger and tube into grain tank in reverse order

Part Number

Description


Quantity

List Price

Net Price

Extended Price Taxed Ind







Invoice To Account No:

SERVICE INVOICE

Internal Used Stock N	o. 560826 (Sold)	Invoice Number:	2450917
		Invoice Date:	7/15/2020
		Location:	30
		Work Order Number:	422060
		Payment Type:	Account
Bus Phone:			
Prv Phone:	Mob Phone:	Page:	35 of 44

Deliver To:

Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO

2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Mob Phone:

JOHN DEERE Make/Model:

PDRV/2WD/650X85R38DLS/750X65F

Meter:

1409

Serial Number: 1H0S690SAG0785341


Eq ID:

SAG0785341

Fleet No:

//S690 CMBS206	Internal						
03M7184		8 X 20 CARBOLT	2.00	0.65	0.65	\$1.30	N
11M7021		COTTER PIN	1.00	0.32	0.32	\$0.32	N
14M7298		8MM FL NUT	2.00	0.79	0.79	\$1.58	Ν
14M7400		LOCK NUT	9.00	1.27	1.27	\$11.43	N
14M7589		LOCK NUT	3.00	2.59	2.59	\$7.77	Ν
19M7785		10X25FL 10	1.00	1.06	1.06	\$1.06	Ν
24M7241		WASHER	2.00	1.38	1.38	\$2.76	Ν
34M7043		SPRING PIN	1.00	0.76	0.76	\$0.76	Ν
49M4821		SHAFT KEY	1.00	2.15	2.15	\$2.15	N
AH214614		SEAL	1.00	20.28	20.28	\$20.28	Ν
AH221739		BRACKET	1.00	126.30	126.30	\$126.30	Ν
AXE69563		Loading Auger, S Series	1.00	982.66	982.66	\$982.66	N
AXE71684		DOOR	1.00	122.64	122.64	\$122.64	N
AXE83882		HOUSING	1.00	2,088.85	2,088.85	\$2,088.85	N
H137916		SHIM	1.00	4.70	4.70	\$4.70	N
H217334		TORSION SP	1.00	8.69	8.69	\$8.69	Ν
H229359		PIN FASTENER	1.00	10.04	10.04	\$10.04	N
H229875		BOLT	6.00	1.83	1.83	\$10.98	Ν
HXE99951		Pin	1.00	16.80	16.80	\$16.80	N







Invoice To Account No:

SERVICE INVOICE

Stock No. 560826 (Sold)	Invoice Number:	2450917
	Invoice Date:	7/15/2020
	Location:	30
	Work Order Number:	422060
	Payment Type:	Account
Mob Phone:	Page:	36 of 44
		Invoice Date: Location: Work Order Number: Payment Type:

Deliver To:

Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO 2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Mob Phone:

Make/Model:

JOHN DEERE

PDRV/2WD/650X85R38DLS/750X65R

Meter:

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

1.00

//S690 CMBS206 Internal

JD10384

BEARING

41.19

41.19

\$41.19

Ν

Labor: \$450.00

Parts: \$3,462.26

OL&M: \$0.00

Misc: \$0.00

Sub-Total: \$3,912.26

//S690 CMBS175 Internal

COMPLAINT:


50 Clean grain elevator upper bearings, shaft, & sprocket, Replace

CORRECTION:

Clean grain elevator upper bearings, shaft, & sprocket, Replace Removed shield in grain tank to expose shaft and pulley removed belt from pulley and removed key removed lock collars and outside bearing flanges and hardware removed bearings from shaft and removed spacers, removed sprocket and shaft found shaft was eaten into in the key way, discarded all parts installed in reverse order with new shaft bearings lock collars sprocket and flanges installed pulley and set to where belt rides on the same plane installed belt onto pulley and installed shield

<u>Part Number</u> 11M7083	Description COTTER PIN	Quantity 2.00	<u>List Price</u> 0.35	Net Price 0.35	Extended Price \$0.70	Taxed Ind N
19M7785	10X25FL 10	3.00	1.06	1.06	\$3.18	Ν
24M7298	WASHER	1.00	0.65	0.65	\$0.65	N
49M6480	SHAFT KEY	1.00	2.87	2.87	\$2.87	N
AH133191	ECCENTRIC	2.00	13.61	13.61	\$27.22	N
H153308	PRESSED FL	4.00	6.88	6.88	\$27.52	N
H153524	KEY	1.00	9.74	9.74	\$9.74	N
H220121	SHAFT	1.00	103.53	103.53	\$103.53	N







Invoice To Account No:

SERVICE INVOICE

Bus Phone: Prv Phone:	Mob Phone:	Page:	37 of 44
•		Payment Type:	Account
		Work Order Number:	422060
		Location:	30
		Invoice Date:	7/15/2020
Internal Used Stock N	lo. 560826 (Sold)	Invoice Number:	2450917

Deliver To:

Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO 2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Make/Model:

JOHN DEERE

PDRV/2WD/650X85R38DLS/750X65R

Meter:

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

//S690 CMBS175 Internal

SPACER 2.00 20.38 20.38 \$40.76 Ν H220234 HXE22458 **CHAIN SPRO** 1.00 100.48 100.48 \$100.48 Ν \$65.00 Ν JD39104 **BALL BEARI** 2.00 32.50 32.50

Labor: \$517.50

Parts: \$381.65

Mob Phone:

OL&M: \$0.00

Misc: \$0.00

Sub-Total: \$899.15

//S690 CMBS395 Internal

COMPLAINT:

51 Unloading auger horizontal right angle gear case, R&R, Recondition

Unloading auger horizontal right angle gear case, R&R, Recondition

After removing unloading augers and tube

Removed grease line and bolt, removed hardware on other side of turret and pulled out gearcase

removed bolts holding end caps on

pulled out shafts, bearings and shims discarded shafts and bearings

pressed new bearings onto shafts

removed seals from end caps and installed new seals, installed end caps and shims torqued to spec


installed shafts into gear case filled with cornhead grease

checked backlash on gears adjusted shims to get .10 of lash

installed gear case in turret installed in reverse order

Part Number 19M7881	<u>Description</u> SCREW	Quantity 10.00	<u>List Price</u> 0.83	Net Price 0.83	Extended Price \$8.30	Taxed Ind N
AN102562	14 Oz. Corn Head grease Tube	1.00	3.87	3.87	\$3.87	N
CE18772	LOCK WASHE	1.00	5.69	5.69	\$5.69	N
CE18774	O-RING	2.00	2.74	2.74	\$5.48	N
CE18775	SHIM	2.00	3.76	3.76	\$7.52	N







Invoice To Account No:	SERVIC	CE INVOICE
Internal Used Stock No. 560826 (Sold)	Invoice Number:	2450917
	Invoice Date:	7/15/2020
	Location:	30
	Work Order Number:	422060
	Payment Type:	Account
Bus Phone:		
Prv Phone: Mob Phone:	Page:	38 of 44
Deliver To:		
Internal Used Stock No. 560826 (Sold)	Make/Model: JOHN DEERE	
PLATTE VALLEY EQUIPMENT CO	PDRV/2WD/650X	85R38DLS/750X65F
2221 COUNTY ROAD Q	Meter: 1409	
PO BOX 1060	 Serial Number: 1H0S690SAG078	25241
FREMONT NE 68025	Serial Number: ThusbausAGu76	99941

//S690 CMBS395 Internal

Labor: \$600.00	Parts: \$583.42	OL&M: \$0.00	Misc: \$	0.00	Sub-Tota	al: \$1,183.42	
DE31554	BEVEL GEAR		1.00	440.43	440.43	\$440.43	N
DE19358	SEAL		2.00	15.02	15.02	\$30.04	N
DE19357	TAPERED ROLL		1.00	82.09	82.09	\$82.09	Ν

Eq ID:

Fleet No:

SAG0785341

//S690 CMBS461 Internal

COMPLAINT:

Bus Phone:

Prv Phone:

52 Unloading auger horizontal auger & tube, R&R

CORRECTION:

Unloading auger horizontal auger & tube, R&R

Removed boot, grain saver door and light strap, discarded grain saver door for being worn through

Mob Phone:


removed outer auger end bolt, dropped hanger bearing and removed, removed auger section, did same thing to other 2 augers

rebuilt 90 degree gearcase installed new augers and timed augers

installed new grain saver door, installed boot

Part Number 11M7012	Description COTTER PIN	Quantity 1.00	<u>List Price</u> 0.24	Net Price 0.24	Extended Price \$0.24	Taxed Ind N
57M11936	ELEC. CONN	9.00	0.76	0.76	\$6.84	N
AH214614	SEAL	1.00	20.28	20.28	\$20.28	N
AH221739	BRACKET	1.00	126.30	126.30	\$126.30	N
AH234554	AUGER	1.00	1,392.59	1,392.59	\$1,392.59	Ν
AH235525	AUGR UNL OUTR*26""""""""""""""""""""""""""""""""""""	1.00	1,740.29	1,740.29	\$1,740.29	N
AT44188	Rivet	4.00	0.73	0.73	\$2.92	N
AXE56290	AUGER	1.00	1,564.80	1,564.80	\$1,564.80	N







invoice			
Interna	Head	St	nck

SERVICE INVOICE

Stock No. 560826 (Sold)	Invoice Number:	2450917
	Invoice Date:	7/15/2020
	Location:	30
	Work Order Number:	422060
	Payment Type:	Account
Mob Phone:	Page:	39 of 44
		Invoice Date: Location: Work Order Number: Payment Type:

Deliver To:

Internal Used Stock No. 560826 (Sold)
PLATTE VALLEY EQUIPMENT CO
2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Mob Phone:

Make/Model:

JOHN DEERE

PDRV/2WD/650X85R38DLS/750X65F

Meter:

1409

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

Labor: \$900	.00	Parts: \$7,936.56	OL&M: \$0.00	Misc:	\$0.00	Sub-To	tal: \$8,836.56	
R44302		Tie Strap, 7.5 "		17.00	0.14	0.14	\$2.38	N
M84309		NUT		15.00	1.17	1.17	\$17.55	Ν
HXE59141		GASKET		1.00	20.40	20.40	\$20.40	N
HXE125955		DOOR		1.00	148.71	148.71	\$148.71	Ν
AXE71684		DOOR		1.00	122.64	122.64	\$122.64	N
//S690 CMBS461 AXE68700	Internal	Housing		1.00	2,770.62	2,770.62	\$2,770.62	N

Gen53- Internal COMPLAINT:

replace wiper blades, fill reservoir


CORRECTION:

Removed wiper blades installed new wiper blades filled fluid reservoir stuck remaining fluid in cab

 Labor: \$75.00	Parts: \$86.26	OL&M: \$0.00	Misc:	\$0.00	Sub-To	otal: \$161.26	
WINDWASH	WASHER FLUID		1.00	3.88	3.88	\$3.88	N
AL204405	WIPER BLAD		1.00	21.14	21.14	\$21.14	N
Part Number AL204404	<u>Description</u> WIPER BLAD		Quantity 1.00	<u>List Price</u> 61.24	Net Price 61.24	Extended Price \$61.24	Taxed Ind N

Gen54- Internal COMPLAINT:







Invoice	То	Acco	unt	No:
---------	----	------	-----	-----

SERVICE INVOICE

2450917 Internal Used Stock No. 560826 (Sold) Invoice Number: 7/15/2020 Invoice Date: Location: 30 Work Order Number: 422060 Account Payment Type: Bus Phone: 40 of 44 Mob Phone: Page: Prv Phone: Deliver To:

Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO

2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Mob Phone:

Make/Model:

JOHN DEERE

PDRV/2WD/650X85R38DLS/750X65F

Meter:

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

Gen54- Internal replace rotary light

CORRECTION:

loosened wing nut an removed beacon light installed new beacon light and tightened wing nut operated light for function

Labor: \$75.00	Parts: \$84.03	OL&M: \$0.00	Misc: \$	00.00	Sub-To	otal: \$159.03	
KENSOL	BRAKE/METAL CLE		2.00	3.60	3.60	\$7.20	N
Part Number AZ101891	<u>Description</u> REVOLVING		Quantity 1.00	76.83	76.83	\$76.83	N

//CS690 CS-13 Internal

COMPLAINT:

replace rear extinguisher

CORRECTION:


Part Number 24M7298	<u>Description</u> WASHER			Quantity 1.00	<u>List Price</u> 0.65	Net Price 0.65	Extended Price \$0.65	Taxed Ind N
TY25183	Fire extinguisher 2.5 g	allon water		1.00	190.30	190.30	\$190.30	N
Labor: \$22.50	Parts: \$190.95	OL&M: \$	50.00	Misc:	\$0.00	Sub-To	tal: \$213.45	

//S690 CMBS490 Internal

COMPLAINT:

56 Radiator propeller bearing, Replace







Invoice To Account No:

SERVICE INVOICE

Internal Used	Stock No. 560826 (Sold)	Invoice Number:	2450917
		Invoice Date:	7/15/2020
*		Location:	30
		Work Order Number:	422060
Y		Payment Type:	Account
Bus Phone:			
Prv Phone:	Mob Phone:	Page:	41 of 44

Deliver To:

Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO

2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Mob Phone:

Make/Model:

JOHN DEERE

PDRV/2WD/650X85R38DLS/750X65F

Meter:

1409

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

//S690 CMBS490 Internal

CORRECTION:

Opened cooler door Installed missing bolt for propeller routed belt for rotary screen closed and locked door

<u>Part N</u> 14M7	umber '303	Description 6MM FL NUT			Quantity 2.00	List Price 0.44	Net Price 0.44	Extended Price \$0.88	Taxed Ind N
19M7	7775	SCREW			2.00	0.76	0.76	\$1.52	N
19M7	'864	SCREW			1.00	0.83	0.83	\$0.83	N
24M7	'389	WASHER			10.00	1.54	1.54	\$15.40	Ν
HXE.	113942	Spacer			1.00	7.43	7.43	\$7.43	N
HXE	154558	Shim			2.00	4.46	4.46	\$8.92	N
Labo	or: \$75.00	Parts: \$34.98	OL&M:	\$0.00	Misc:	\$0.00	Sub-To	otal: \$109.98	· · · · ·


Gen- Internal

COMPLAINT:

Install cross auger shut off (sp with saul 3600

CORRECTION:







Invoice To Account No:

SERVICE INVOICE

Internal Used Stock N	lo. 560826 (Sold)	Invoice Number:	2450917
		Invoice Date:	7/15/2020
		Location:	30
		Work Order Number:	422060
		Payment Type:	Account
Bus Phone:			
Prv Phone:	Mob Phone:	Page:	42 of 44
Deliver To:			

Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO

2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Mob Phone:

Make/Model:

JOHN DEERE

PDRV/2WD/650X85R38DLS/750X65R

Meter:

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

Gen- Internal

removed snaprings from end of augers

removed set screws and air hammered sprockets off shafts

installed drill sleeve over auger shafts and drilled holes 3 in deep on each auger shaft, tapped holes

installed new key to shafts, assembled sprockets to clutches and installed onto augers

applied loctite to bolts for clutches and tightened

took level and made sure sprockets were on same plain for smooth chain operation

installed drive chain

installed strap to hold clutches together

notched out piece of door frame for harness to fit through and routed foot pedal harness behind the seat to foot pedal switch

routed foot pedal and harness back to module

routed unloading engagement harness from main engine gearcase to module

hooked power and ground wires straight to battery disconnect and battery ground cable

notched out battery box cover for wiring to fit through

operated unloading auger cleanout


 Labor: \$600.00	Parts: \$2,959.64 OL&	M: \$0.00	Misc: \$0	0.00	Sub-To	tal: \$3,559.64	•
LANUDJD2000K			1.00	2,950.00	2,950.00	\$2,950.00	N
T13814	CLAMP		4.00	1.33	1.33	\$5.32	N
R44302	Tie Strap, 7.5 "		12.00	0.14	0.14	\$1.68	Ν
19M7775	SCREW		1.00	0.76	0.76	\$0.76	Ν
14M7303	6MM FL NUT		1.00	0.44	0.44	\$0.44	Ν
14M7298	8MM FL NUT		1.00	0.79	0.79	\$0.79	N
Part Number 03M7184	<u>Description</u> 8 X 20 CARBOLT	<u>'</u>	Quantity 1.00	<u>List Price</u> 0.65	Net Price 0.65	Extended Price \$0.65	Taxed Ind N

//S690 CMBS267 Internal

COMPLAINT:

58 install batteries







Invoice To Account No:

SERVICE INVOICE

Internal Used Stock No. 560826 (Sold)	Invoice Number:	2450917
	Invoice Date:	7/15/2020
	Location:	30
	Work Order Number:	422060
	Payment Type:	Account
Bus Phone:		
Prv Phone: Mob Phone:	Page:	43 of 44
Deliver To:		
Internal Used Stock No. 560826 (Sold) PLATTE VALLEY EQUIPMENT CO	Make/Model: JOHN DEERE PDRV/2WD/650	X85R38DLS/750X65F

2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone:

Prv Phone:

Mob Phone:

Meter:

1409

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

//S690 CMBS267 Internal

CORRECTION:

Removed battery shield and switched battery's off loosened cable ends and removed cables from battery's loosened clamps removed and installed new battery's installed cables and tightened installed clamps modified battery box and on combine cut small notches for power cable for unloading auger clean out clutches installed loom to wiring and taped installed shield made sure wires werent going to rub


Part Number	
TY26783A	

Description
BATTERY,WET,12V,BCI D5,CCA 1400

Quantity 2.00 List Price 437.58 Net Price 437.58 Extended Price \$875.16

Taxed ind







Grand Total: \$54,030.17


www.plattevalleyequipment.com

Invoice To Account No:				SERVICE INVOICE					
Internal Used Stock No. 560	0826 (Sold)			Invoice N	lumber:	2450917			
				Invoi	ce Date:	7/15/2020			
· V ·				L	.ocation:	30			
				Work Order	Number:	422060			
				Payme	ent Type:	Account			
Bus Phone:									
Prv Phone:	Mob Phone:				Page:	44 of 44			
Deliver To:		Additional to the second secon							
Internal Used Stock No. 56	0826 (Sold)			Make/Model:	JOHN DEERE				
PLATTE VALLEY EQUIPME	NT CO				PDRV/2WD/650X85	R38DLS/750X65R			
2221 COUNTY ROAD Q				Meter:	1409				
PO BOX 1060 FREMONT NE 68025			***	Serial Numbe	r: 1H0S690SAG07853	341			
				Eq ID:	SAG0785341				
Bus Phone:				•	3A30703341				
Prv Phone:	Mob Phone:			Fleet No:					
//S690 CMBS267 Internal	0000000	15. "	0.0	70.0	20.00	644400 N			
TY26783A-CR	CORE for:Wet Charge	Battery	2.0	00 72.0	0 72.00	\$144.00 N			
Labor: \$225.00	Parts: \$1,019.16	OL&M: \$0.00	Mis	c: \$0.00	Sub-Total:	\$1,244.16			
Miscellaneous Charges:									
Service Accessories						\$125.00			
					Labor:	\$18,037.50			
					Parts:	\$39,669.67			
					OL&M:	\$0.00			
					Misc:	(\$3,677.00)			
					Sales Tax:	\$0.00			

TERMS AND CONDITIONS

* * * DOCUMENT COPY * * *







Invoice To Account No: 4

SERVICE INVOICE

WARRANTY CUSTOMER	Invoice Number:	2450965
John Deere Warranty	Invoice Date:	7/15/2020
	Location:	30
	Work Order Number:	422060
1.4	Payment Type:	Account
Bus Phone:		
Prv Phone: Mob Phone:	Page:	1 of 2

Deliver To:

PLATTE VALLEY EQUIPMENT CO

2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone: (402)721-9111

Prv Phone: (800)844-8818

Mob Phone: (402)270-2628

JOHN DEERE Make/Model:

PDRV/2WD/650X85R38DLS/750X65F

Meter: 1409

Serial Number: 1H0S690SAG0785341

Eq ID: SAG0785341

Fleet No:

//S690 CMBS693 Warranty

COMPLAINT:

Machine has excessive blow by

CAUSE:

faulty venturi vent

CORRECTION:

Drained oil inspected for mixing of oil and coolant filled oil changed filter, filled cooling system with coolant installed pressure gauge to cooling system reservoir operated engine to get to operating temperature pressure stayed around 12 psi got speed sensor and digital volt meter withflex probes and operated engine and tested speed of impeller and speed was fluctuating inspected open crank case vent removed hoses from vent and removed vent from engine bracket found vent impeller was seized installed new open crank vent

Part Number

Description


Quantity

List Price

Net Price

Extended Price Taxed Ind








Invoice To Account No: 4				SERVICE	INVOICE
WARRANTY CUSTOMER			Invoice	Number:	2450965
John Deere Warranty			Invo	ice Date:	7/15/2020
				Location:	30
			Work Order		422060
			Paym	ent Type:	Account
Bus Phone:				Danas	2 of 2
Prv Phone:	Mob Phone:			Page:	2012
Deliver To:					
PLATTE VALLEY EQUIPMENT 2221 COUNTY ROAD Q	rco		Make/Model	JOHN DEERE PDRV/2WD/650X85	R38DLS/750X65F
PO BOX 1060			Meter:	1409	
FREMONT NE 68025			Serial Numb	er: 1H0S690SAG07853	41
Bus Phone: (402)721-9111			Eq ID:	SAG0785341	
Prv Phone: (800)844-8818	Mob Phone: (402)2	70-2628	Fleet No:		
	A A A A A A A A A A A A A A A A A A A				
//S690 CMBS693 Warranty RE550022	VENT		1.00 1,387	62 1,387.62 \$	1,387.62 N
Labor: \$697.17	Parts: \$1,387.62	OL&M: \$0.00	Misc: \$0.00	Sub-Total:	\$2,084.79
		The state of the s			
					PC07.47
				Labor: Parts:	\$697.17 \$1,387.62
				OL&M:	\$0.00
				Misc:	\$0.00
				Sales Tax:	\$0.00
* * * DOCUMENT C	ODV * * *			Grand Total:	\$2,084.79

TERMS AND CONDITIONS

* * * DOCUMENT COPY * * *

Received by:	Date:
•	







SERVICE INVOICE

www.plattevalleyequipment.com

Invoice to Account No: 4	OLIVAI	JE HAAOIOE
WARRANTY CUSTOMER	Invoice Number:	2450973
John Deere Warranty	Invoice Date:	7/15/2020
	Location:	30
	Work Order Number:	422060
	Payment Type:	Account
Rus Phone:		

Prv Phone: Deliver To:

PLATTE VALLEY EQUIPMENT CO

2221 COUNTY ROAD Q

PO BOX 1060

FREMONT NE 68025

Bus Phone: (402)721-9111

Prv Phone: (800)844-8818

Mob Phone: (402)270-2628

Mob Phone:

JOHN DEERE Make/Model:

PDRV/2WD/650X85R38DLS/750X65R

1 of 3

Meter: 1409

Serial Number: 1H0S690SAG0785341

Page:

Eq ID: SAG0785341

Fleet No:

//S690 CMBS715 Warranty

COMPLAINT:

ECU 641.13 error code

CAUSE: faulty turbo

CORRECTION:

Code 641.13 for vgt actuator

checked actuator and linkage for rough spots in travel performed calibration several times failed every time

went and accessed the machine through service advisor looked at encoder count and found it was well above spec

Removed exhaust pipe clamp and gasket

removed intake pipe bolts and gasket, removed charged air pipe clamp and gasket

removed coolant lines from actuator

removed supply and drain lines

disconnected wiring connectors and clamps and brackets

removed exhaust manifold to turbo exhaust flange nuts

removed turbo and removed gasket for exhaust flange

cleaned mating surfaces

removed orings on coolant lines and supply line and installed new

installed new exhaust flange gasket and sat new turbo onto manifold

applied never seize to study and installed turbo exhaust flange nuts and torqued to spec

installed new gasket for turbo drain line and installed hardware and torqued

installed coolant lines to actuator and tightened

installed supply line and tightened

installed new gasket and clamp for exhaust pipe and tightened clamp

installed new gasket and clamps for intake piping

installed brackets for wiring and routed wiring and clamped and connected to harness

performed value reset through service advisor

ran machine checked for codes code now gone

Part Number 03M7185

Description **BOLT**

Quantity 17.00 List Price 0.35 **Net Price** 0.35

Extended Price \$5.95

Taxed Ind



SENSOR

GASKET

RE519144

RE540355





www.plattevalleyequipment.com

Invoice To Account No: 4				SERVI	CE INVOI	CE
WARRANTY CUSTOMER			Invoice Num		2450	
John Deere Warranty			Invoice E	ate:	7/15/	/2020
		133	Loca			30
		∥ Wo	ork Order Num			22060 count
			Payment T	ype:	AC	Count
Bus Phone: Prv Phone:	Mob Phone:		Р	age:		2 of 3
Deliver To:	West News	JL				
PLATTE VALLEY EQUIPME 2221 COUNTY ROAD Q	NT CO	Mak	e/Model: J0	OHN DEERE DRV/2WD/650	X85R38DLS/750	X65F
PO BOX 1060		Met	er: 14	109		
FREMONT NE 68025		Seri	al Number: 11	H0S690SAG07	85341	İ
		Eq I		AG0785341		
Bus Phone: (402)721-9111	Mark Disease (400)070 2000	11 '	et No:	100700011		
Prv Phone: (800)844-8818	Mob Phone: (402)270-2628	1166	it IVO.			
//S690 CMBS715 Warranty						
14M7296	10 MM Flanged Nut	9.00	1.10	1.10	\$9.90	Ν
14M7298	8MM FL NUT	12.00	0.79	0.79	\$9.48	N
19M7783	10X16FL 10	4.00	0.90	0.90	\$3.60	Ν
19M7785	10X25FL 10	1.00	1.06	1.06	\$1.06	Ν
19M7835	10X35FL 10	4.00	0.79	0.79	\$3.16	Ν
24M7296	WASHER	10.00	0.97	0.97	\$9.70	Ν
24M7298	WASHER	9.00	0.65	0.65	\$5.85	N
DZ100375	GASKET	1.00	6.24	6.24	\$6.24	Ν
DZ102071	Turbocharger, Has Core	1.00	3,188.75	3,188.75	\$3,188.75	Ν
DZ102071-CR	CORE for:Turbocharger	-1.00	275.00	275.00	(\$275.00)	Ν
DZ114164	O-RING	1.00	24.30	24.30	\$24.30	Ν
R28776	O-RING	2.00	1.43	1.43	\$2.86	N
R522023	GASKET	1.00	6.66	6.66	\$6.66	N
R527611	STUD	3.00	18.70	18.70	\$56.10	Ν
R528620	GASKET	1.00	39.67	39.67	\$39.67	Ν
RE285844	CLAMP	1.00	61.43	61.43	\$61.43	Ν
RE289839	CLAMP	1.00	33.68	33.68	\$33.68	N

1.00

1.00

33.10

10.10

33.10

10.10


\$33.10

\$10.10

Ν

Ν








Invoice To Account No: 4						SERVICE	INVO	ICE
WARRANTY CUSTOMER				Invo	ice Numl	per:	245	0973
John Deere Warranty					Invoice D	ate:	7/15	5/2020
			1		Locat	ion:		30
					rder Num		-	22060
r an				Pa	ayment Ty	/pe:	Ad	ccount
Bus Phone:					_			2 -4 2
Prv Phone:	Mob Phone:				Pa	ige:		3 of 3
Deliver To:								
PLATTE VALLEY EQUIPMEN 2221 COUNTY ROAD Q	т со			Make/Mo	uui.	HN DEERE PRV/2WD/650X85	R38DLS/750)X65F
PO BOX 1060				Meter:	14	09		•
FREMONT NE 68025				Serial Nu	mber: 1H	0S690SAG07853	41	
				Eq ID:	SA	G0785341		
Bus Phone: (402)721-9111	** 1 ml (400)0	70.000						
Prv Phone: (800)844-8818	Mob Phone: (402)2	70-2628		Fleet No:	pro-			
//S690 CMBS715 Warranty RE553167	GASKET		1.0	0	27.48	27.48	\$27.48	N
Labor: \$996.66	Parts: \$3,264.07	OL&M: \$0.00	Mis	c: \$0.00)	Sub-Total:	\$4,260.73	
	MANAGE TO SERVICE TO S					Labor:	\$9	96.66
						Parts:	\$3,2	264.07
						OL&M:		\$0.00
						Misc:		\$0.00
						Sales Tax:		\$0.00
* * * DOCUMENT	COPY * * *					Grand Total:	\$4,2	260.73

TERMS AND CONDITIONS

* * * DOCUMENT COPY * * *

in the state of th	Datas
Received by:	Date:
1 (COCIVOR DY	







Invoice To Account No: 133526

SERVICE INVOICE

KENNETH JOHNSON	Invoice Number:	2468538
1210 COUNTY RD L	Invoice Date:	7/29/2020
OAKLAND NE 68045	Location:	30
	Work Order Number:	442256
	Payment Type:	Finance
Bus Phone: 4026855314		4 - 6 2
Prv Phone: (402)380-1495 Mob Phone: (402)380-1495	Page:	1 of 3

Deliver To:

KENNETH JOHNSON 1210 COUNTY RD L		Make/Model: JOHN DEERE S690
OAKLAND NE 68045		Meter:
		Serial Number: 1H0S690SAG0785341
Bus Phone: (402)685-5314		Eq ID: SAG0785341
` ,	Mob Phone: (402)380-1495	Fleet No:

Gen1- Retail COMPLAINT:

install camera in grain tank

CORRECTION:
went into grain tank
drilled holes to mount camera
mounted camera and tightened hardware
adjusted camera view to where grain level is visible
ran wiring from camera to cab wall connectors
zip tied wiring to existing harness down to cab wall connector
plugged in connector went into cab and made sure camera was working properly


Labor: \$225.00	Parts: \$212.28	OL&M: \$0.00	Misc: S	0.00	Sub-To	otal: \$437.28	
H77698	TIE BAND		20.00	0.35	0.35	\$7.00	Υ
A-VS1C110	TELEVISION		1.00	124.19	124.19	\$124.19	Υ
Part Number A-GS3C	<u>Description</u> ELECTRICAL		Quantity 1.00	81.09	81.09	\$81.09	Y

Gen2- Retail COMPLAINT:

install side hill kit (BXE10076)

CORRECTION:







Invoice To Account No: 133526

SERVICE INVOICE

2468538 Invoice Number: KENNETH JOHNSON Invoice Date: 7/29/2020 1210 COUNTY RD L OAKLAND NE 68045 30 Location: 442256 Work Order Number: Finance Payment Type: Bus Phone: 4026855314

Prv Phone: (402)380-1495

KENNETH JOHNSON 1210 COUNTY RD L OAKLAND NE 68045

Bus Phone: (402)685-5314

Prv Phone: (402)380-1495

Deliver To:

Mob Phone: (402)380-1495

JOHN DEERE S690 Make/Model:

Page:

Meter:

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

Gen2- Retail

Removed shields and removed black separator covers installed louvers on to shaker pan and tightened hardware installed louvers on to front chaffer and tightened hardware raised chopper, removed wiring from chaffer actuator and removed harness from rear chaffer frame panel removed chaffer actuator cover removed rear panel on chaffer frame removed bolts and removed chaffer installed louvers on front of chaffer frame installed louvers and agitators to chaffer installed chaffer and rear panel in reverse order installed wiring installed agitators on chaffer frame ran combine for operation

Mob Phone: (402)380-1495

Part Number BXE10076 Description COMPLETE GOO

Quantity 1.00


List Price 1,282.60

Net Price 1,179.99

Extended Price Taxed Ind \$1,179.99

2 of 3








invoice To Account No: 133526					INVOICE
KENNETH JOHNSON 1210 COUNTY RD L			Invoice Number		2468538 7/29/2020
OAKLAND NE 68045			Locat		30
OFFICE THE GOOTO			Work Order Num		442256
			Payment Ty		Finance
Bus Phone: 4026855314				, 1	
Prv Phone: (402)380-1495	Mob Phone: (402)380-1495	Pa	nge:	3 of 3
Deliver To:					
KENNETH JOHNSON			Make/Model: JC	HN DEERE S690	
1210 COUNTY RD L					
OAKLAND NE 68045			Meter:		
			Serial Number: 1F	10S690SAG07853	41
D Di (400)005 5314			Eq ID: SA	AG0785341	
Bus Phone: (402)685-5314 Prv Phone: (402)380-1495	Moh Phone: (402)380-1495	Fleet No:		
11V1 Holle. (402)000-1400	Mos Thomas				
Gen2- Retail					****
BXE10476	Shoe Kit		1.00 1,009.80	929.02	\$929.02 Y
Labor: \$1,144.50	Parts: \$2,109.01	OL&M: \$0.00	Misc: \$0.00	Sub-Total:	\$3,253.51
	INVOICE CONTA	INS \$183.39 DISCOUNT			
Miscellaneous Charges: Service Accessories					\$68.48
		Finance Information		Labor:	\$1,369.50
		Type: Multi-use Acct US	Auth. No: 401979	Parts:	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
		Merchant No: 48000244		OL&M:	\$0.00
		Card No: xxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxxx		Misc:	\$68.48
,		-	COMBINE PARTS/SERVICE	Sales Tax:	\$206.77
		Credit Plan: 249 PUF	RCHASE	Grand Total:	\$3,966.04
* * * DOCUMENT	COPY * * *				

TERMS AND CONDITIONS

This purchase(s) is subject to the terms of the Multi-Use Account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

Received by:	Date:
(cocived by:	







SERVICE INVOICE

www.plattevalleyequipment.com

11110100 1071000011111101							
Internal Used Stock I	No. 560826 (Sold)	Invoice Number:	2512226				
		Invoice Date:	8/31/2020				
		Location:	30				
		Work Order Number:	445504				
		Payment Type:	Account				
Bus Phone:							
Prv Phone:	Mob Phone:	Page:	1 of 2				
Deliver To:							
Internal Used Stock KENNETH JOHNSON	` ,	Make/Model: JOHN DEERE PDRV/2WD/650X85R	38DLS/750X65F				
1210 COUNTY RD L		Meter:					
OAKLAND NE 68045		Serial Number: 1H0S690SAG078534	1				
Bus Phone:		Eq ID: SAG0785341					
Prv Phone:	Mob Phone:	Fleet No:					

Gen1- Internal COMPLAINT:

Invoice To Account No:


replace cracked windshield

CORRECTION:

Removed handles from inner roof removed wiring for lights on lower fascia, removed mounting bolts and removed fascia removed cab roof front piece disconnected wiring from wiper removed motor mounting bolts and removed motor installed new windshield and installed removed pieces back in reverse order

Part Number	<u>Description</u>	Quantity	<u>List Price</u>	Net Price	Extended Price	laxed Ind
24M7100	WASHER	1.00	0.59	0.57	\$0.57	N








nvoice To Account No:		SERVICE INVOICE				
Internal Used Stock No. 5	560826 (Sold)		Invoice Num	ber:	2512226	
			Invoice (Date:	8/31/2020	
			Loca		30	
			Work Order Nun		445504	
1.0			Payment 1	Гуре:	Account	
Bus Phone:			_		2 of 2	
Prv Phone:	Mob Phone:		P	'age:	2012	
Deliver To:						
Internal Used Stock No. S KENNETH JOHNSON	560826 (Sold)			OHN DEERE DRV/2WD/650X85R3	8DLS/750X65F	
1210 COUNTY RD L			Meter:			
OAKLAND NE 68045			Serial Number: 1	H0S690SAG0785341		
Bus Phone:			Eq ID: S	AG0785341		
Prv Phone:	Mob Phone:		Fleet No:			
Gen1- Internal			4.00 0.707.50	4 000 00	00.00 N	
KXE10292	WINDSHIELD		1.00 2,767.52	1,800.23 \$1,8	00.23 N	
Labor: \$740.40	Parts: \$1,800.80	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$2	2,541.20	
	INVOICE CONTAINS	\$967.31 DISCOUNT				
Miscellaneous Charges:						
Service Accessories				•	\$37.02	
				Labor:	\$740.40	
				Parts:	\$1,800.80	
				OL&M:	\$0.00	
				Misc:	\$37.02	
				Sales Tax:	\$0.00	
The transfer of the transfer o	UT CODY * * *			Grand Total:	\$2,578.22	

TERMS AND CONDITIONS

Received by:	Date:
Necessed by,	







SERVICE INVOICE

www.plattevalleyequipment.com

Internal Used	Stock No. 560826 (Sold)	Invoice Number:	2544441
		Invoice Date:	9/21/2020
		Location:	30
- 4		Work Order Number:	452347
		Payment Type:	Account
Bus Phone:			4 . 6 4
Prv Phone:	Mob Phone:	Page:	1 of 4
Deliver To:			
Internal Used KENNETH JC	Stock No. 560826 (Sold) DHNSON	Make/Model: JOHN DEERE PDRV/2WD/650X85R38	DLS/750X65F
1210 COUNT		Meter: 1410	
OAKLAND N	E 68045	Serial Number: 1H0S690SAG0785341	
Bus Phone:		Eq ID: SAG0785341	

Fleet No:

Gen1- Internal COMPLAINT: 01 check reverser

Prv Phone:

Invoice To Account No:

CORRECTION:

inspected reverser and found front seal leaking. remove shields, belt, and pulley. drained reverser. removed cover and seal. removed old seal, cleaned sealing surfaces and installed new seal and cover. re installed pulley and belt and tensioned belt. test ran machine and it operates leak free at this time.

Labor: \$194.96	Parts: \$368.82	OL&M: \$0.00	Misc: \$	0.00	Sub-To	otal: \$563.78	
TY26408	qt HD460 full syn gear	lube	6.00	29.91	29.91	\$179.46	N
AH216871	SEAL		1.00	22.03	22.03	\$22.03	N
Part Number AH215259	Description SEAL		Quantity 1.00	List Price 167.33	Net Price 167.33	Extended Price \$167.33	<u>Taxed Ind</u> N

Gen2- Internal COMPLAINT: 02 bin extensions

CORRECTION:


had to use ratchet straps and pry bars and punches to get bin extensions to line up to install clips.

Mob Phone:

Part Number	<u>Description</u>		Quantity	<u>List Price</u>	Net Price	Extended Price	Taxed Ind
AH121475	SENSOR		1.00	44.86	44.86	\$44.86	N
Labor: \$152.20	Parts: \$44.86	OL&M: \$0.00	Misc: \$	60.00	Sub-To	tal: \$197.06	

Gen3- Internal COMPLAINT:







Invoice To Account No:			SERVICE INVOIC				
Internal Used Stock No. 560	0826 (Sold)	Invoice N	umber:	2544441			
	,	Invoid	ce Date:	9/21/2020			
		L.	ocation:	30			
		Work Order N	lumber:	452347			
		Payme	nt Type:	Account			
Bus Phone:			_	2 of 4			
Prv Phone:	Mob Phone:		Page:	2014			
Deliver To:							
Internal Used Stock No. 56 KENNETH JOHNSON	50826 (Sold)	Make/Model:	JOHN DEERE PDRV/2WD/650X85	R38DLS/750X65F			
1210 COUNTY RD L		Meter:	1410				
OAKLAND NE 68045		Serial Number	: 1H0S690SAG07853	41			
D Dhana		Eq ID:	SAG0785341				
Bus Phone: Prv Phone:	Mob Phone:	Fleet No:					

Gen3- Internal 03 replace bin full sensor

CORRECTION:

replaced bent bin full sensor

Part Number	Description		Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH226058	PULLEY		2.00	130.02	130.02	\$260.04	N
Labor: \$0.00	Parts: \$260.04	OL&M: \$0.00	Misc: \$	0.00	Sub-To	otal: \$260.04	

Gen4- Internal COMPLAINT:

04 replace reverser pulley

CORRECTION:

removed and replaced feederhouse idler pulley while repairing reverser.

Labor: \$54.21	Parts: \$0.00	OL&M: \$0.00	Misc: \$0.00	Sub-Total: \$54.21
,				


Gen5- Internal COMPLAINT:

05 get customer started

CORRECTION:

showed customer where to grease, what to change on the machine from corn to beans. had problems when trying to lower feederhouse drum down, had to remove nut part way to get it to turn and then tighten back up, informed customer that lever would have to be replaced. went and set machine settings and made a couple rounds with customer to fine tune machine.








nvoice To Account No:						SERVI	CE INVO)ICE
Internal Used Stock No. 56082	26 (Sold)				Invoice Nu	mber:	25	44441
The state of the s	,				Invoice	Date:	9/2	21/2020
					Lo	cation:		30
				l w	ork Order Nu	ımber:		452347
					Payment	t Type:	1	Account
Bus Phone:						_		3 of 4
Prv Phone:	Mob Phone:					Page:		3 01 4
Deliver To:	· · · · · · · · · · · · · · · · · · ·							
Internal Used Stock No. 5608 KENNETH JOHNSON	26 (Sold)			Ma		JOHN DEERE PDRV/2WD/650	X85R38DLS/7	50X65F
1210 COUNTY RD L				∥ _{Me}	ter	1410		
OAKLAND NE 68045							705241	
						1H0S690SAG0	765541	
Bus Phone:				Eq	ID:	SAG0785341		1
Prv Phone:	Mob Phone:			Fle	et No:			
Gen6- Internal						-		
Gen6- Internal COMPLAINT: 06 moisture sensor has codes								
CORRECTION: machine had codes for moisture and now machine operates erro		s than normal.	diagnosed	and replaced mo	isture sensor	r motor. test ran		
Part Number AXE13658	Description SENSOR			Quantity 1.00	<u>List Price</u> 252.88		Extended Price \$252.88	Taxed Ind N
Labor: \$122.20	Parts: \$252.88	OL&M:	\$0.00	Misc:	\$0.00	Sub-To	otal: \$375.08	
Gen8- Internal COMPLAINT: 08 unloading auger light inop. CORRECTION:								
replaced unloading auger light.	Description			Quantity	List Price	Net Price	Extended Price	Taxed inc
Part Number	Pesculation			Manifelt	22177 - 7191			








Invoice To Account No:				SERVICE INVOICE				
Internal Used Stock No.	560826 (Sold)			nvoice Numb		2544441		
· · · · · · · · · · · · · · · · · · ·	000020 (00.0)			Invoice Da	te:	9/21/2020		
*				Locati	on:	30		
	,		Wor	k Order Numb	er:	452347		
				Payment Ty	pe:	Account		
Bus Phone:						4 - 6 4		
Prv Phone:	Mob Phone:			Pag	ge:	4 of 4		
Deliver To:								
Internal Used Stock No	. 560826 (Sold)		Make		HN DEERE	D20D1 0/750V650		
KENNETH JOHNSON						R38DLS/750X65F		
1210 COUNTY RD L			Mete	r: 141	0			
OAKLAND NE 68045			Seria	l Number: 1H0	S690SAG07853	41		
			Eq IC): SA	G0785341			
Bus Phone:	Mob Phone:		Fleet	No:				
Prv Phone:	IVIOD FIIOTIE.		1,1000	110.		AND THE STATE OF T		
Gen8- Internal			4.00	40.07	40.07	\$16.27 N		
AH208904	BULB		1.00	16.27	16.27	\$16.27 N		
Labor: \$0.00	Parts: \$16.27	OL&M: \$0.00	Misc: \$	0.00	Sub-Total:	\$16.27		
Miscellaneous Charges Service Accessories	3:					\$65.62		
					Labor:	\$1,312.42		
					Labor: Parts:	\$942.87		
					OL&M:	\$0.00		
						\$65.62		
					Misc: Sales Tax:	\$0.00		
·						\$2,320.91		
THE A PROPERTY	THE CODY + + +				Grand Total:	φ ∠ ,3 ∠ U.91		

TERMS AND CONDITIONS

*** DOCUMENT COPY * * *

Received by:	Date:
--------------	-------







Invoice To Account No: 133526

Prv Phone: (402)380-1495

SERVICE INVOICE

2544444 Invoice Number: KENNETH JOHNSON 1210 COUNTY RD L Invoice Date: 9/21/2020 OAKLAND NE 68045 30 Location: 452347 Work Order Number: Finance Payment Type: Bus Phone: 4026855314 1 of 3

Deliver To:

KENNETH JOHNSON 1210 COUNTY RD L OAKLAND NE 68045

JOHN DEERE Make/Model:

PDRV/2WD/650X85R38DLS/750X65R

Meter:

1410

Page:

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

Bus Phone: (402)685-5314 Prv Phone: (402)380-1495

Mob Phone: (402)380-1495

Mob Phone: (402)380-1495

//S690 CMBS602 Retail

COMPLAINT:

07 Lower outer straw chopper drive belt, Replace

CORRECTION:

Remove shields.

Relieve tension on discharge beater belt and remove from drive sheave. Relive tension on inner chopper drive belt and remove from drive sheave. Relieve tension on outer chopper drive belt.

Remove and replace outer chopper belt.

Assemble in reverse order and re-tension belts.

<u>Part Number</u> HXE124868	<u>Description</u> V-BELT CHOPP UPPE	ER DRIVE 3GRV 132.2" LO	Quantity 1.00	<u>List Price</u> 474.39	<u>Net Price</u> 474.39	\$474.39	Taxed Ind Y
Labor: \$135.00	Parts: \$474.39	OL&M: \$0.00	Misc: \$	0.00	Sub-To	tal: \$609.39	

//S690 CMBS344 Retail

COMPLAINT:

09 Unloading auger drive belt, R&R


CORRECTION:

Unloading auger drive belt, R&R

Extended Price List Price Net Price Taxed Ind Quantity Description Part Number 166.50 \$166.50 1.00 166.50 AH233198 BELT SET Sub-Total: \$391.50 Misc: \$0.00 Parts: \$166.50 OL&M: \$0.00 Labor: \$225.00

Gen10- Retail COMPLAINT:







Invoice To Account No: 133526

SERVICE INVOICE

KENNETH JOHNSON	Invoice Number:	2544444
1210 COUNTY RD L	Invoice Date:	9/21/2020
OAKLAND NE 68045	Location:	30
	Work Order Number:	452347
	Payment Type:	Finance
Bus Phone: 4026855314		
Prv Phone: (402)380-1495 Mob Phone: (402)380-1495	Page:	2 of 3

Deliver To:

JOHN DEERE Make/Model: KENNETH JOHNSON PDRV/2WD/650X85R38DLS/750X65R 1210 COUNTY RD L OAKLAND NE 68045 Meter: 1410 Serial Number: 1H0S690SAG0785341 Eq ID: SAG0785341 Bus Phone: (402)685-5314 Fleet No: Mob Phone: (402)380-1495 Prv Phone: (402)380-1495


Gen10- Retail 10 belt slippage codes

CORRECTION:

when head was run machine had slippage codes for rh outer belt. jumped sensor and codes went away, customer went to shop for sensor, removed guards and shoes, detensioned belt, removed shields over sensor, installed new sensor, re installed shields and belts and guards and shoes, tensioned belt and test ran and now machine operates error code free.

rat (vuliber Description	Quantity List Price Net Price Extended Price Taxed Ind	<u>Description</u>	Part Number
--------------------------	--------------------------------------------------------	--------------------	-------------







Invoice To Account No: 13352	6				SERVICE	INVOICE
KENNETH JOHNSON				Invoice N	umber:	2544444
1210 COUNTY RD L				Invoic	e Date:	9/21/2020
OAKLAND NE 68045				Lo	ocation:	30
] ,	Work Order N	umber:	452347
				Paymer	nt Type:	Finance
Bus Phone: 4026855314						0.10
Prv Phone: (402)380-1495	Mob Phone: (402)380-1495			Page:	3 of 3
Deliver To:						
KENNETH JOHNSON			N	lake/Model:	JOHN DEERE PDRV/2WD/650X85	DOOD! CITENVEED
1210 COUNTY RD L					PDRV/2WD/650X65	K30DF2//30V03h
OAKLAND NE 68045			N	leter:	1410	
			s	erial Number	1H0S690SAG07853	41
(100)005 5044			E	iq ID:	SAG0785341	
Bus Phone: (402)685-5314	Mob Dhono:	402)380-1495	-	leet No:		
Prv Phone: (402)380-1495	Wob Flione.	402)300-1433	IĽ	100(110.		
Gen10- Retail						
AXE20081	SENSOR		1.00	95.66	95.66	\$95.66 Y
Labor: \$600.00	Parts: \$95.66	OL&M: \$0.00	Misc	: \$0.00	Sub-Total:	\$695.66
Miscellaneous Charges:						
Service Accessories						\$48.00
		Finance Information			Labor:	\$960.00
		Type: Multi-use Acct US	Auth. No:	880559	Parts:	\$736.55
		Merchant No: 48000244			OL&M:	\$0.00
And the second second		Card No: xxxxxxxxxxxx2			Misc:	\$48.00
			COMBINE PART	S/SERVICE	Sales Tax:	\$95.96
· .		Credit Plan: 249 PUF	RCHASE		Grand Total:	\$1,840.51
* * * DOCUMENT	COPY * * *					


TERMS AND CONDITIONS

Repayment Terms:

This purchase(s) is subject to the terms of the Multi-Use Account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

•	
Received by:	Date:







Page:

1 of 2

www.plattevalleyequipment.com

210 COUNTY RD L	SERVI	CE INVOICE
KENNETH JOHNSON	Invoice Number:	2594291
1210 COUNTY RD L	Invoice Date:	10/15/2020
OAKLAND NE 68045	Location:	30
	Work Order Number:	464685
	Payment Type:	Finance
Bus Phone: 4026855314		

Deliver To:

678109155121071537 Retail

Prv Phone: (402)380-1495

COMPLAINT:

John Deere has been monitoring JDLink machine data for machines setting DTC(s): PTP 524232.0

Mob Phone: (402)380-1495

PTP 524232.1

PTP 524232.2

PTP 524232.3

PTP 524232.4

PTP 524232.7. These DTCs indicate a potential failure of the ProDrive park brake sump valve. Failure to address this issue could lead to limited machine function and inability to drive the machine.

PTP - 524232.4 - YELLOW PTP 524232.04 Park brake pressure sensor circuit fault. - Return to park to attempt recovery. - 1579.1 Hours - 2020-10-14 03:55

CORRECTION:

replaced park sump block valve, test ran and machine still has ptp 524232.04 followed diagnostics and found park brake sensor broken, removed and replaced sensor and machine now operates normally and error code free.

Part Number AXE43127	<u>Description</u> SENSOR		Quantity 1.00	<u>List Price</u> 138.93	Net Price 138.93	Extended Price \$138.93	Taxed Ind Y
AXE64836	VALVE		1.00	12.99	12.99	\$12.99	Υ
Labor: \$266.35	Parts: \$151.92	OL&M: \$0.00	Misc: \$	0.00	Sub-To	otal: \$418.27	

/LD Retail COMPLAINT:


02 Service Call load & drive time

CORRECTION:

Service Call load & drive time

Miscellaneous Description Quantity List Price Net Price Extended Price Taxed Ind







Invoice To Account No: 13352	6						SERVICE	INV	DICE
KENNETH JOHNSON	ALC MINISTER IN THE STATE OF TH				Invoice	e Numbe	ər:	25	594291
1210 COUNTY RD L					Inv	voice Da	te:	10.	/15/2020
OAKLAND NE 68045						Location	on:		30
					Work Orde	er Numb	er:		464685
					Payı	ment Typ	oe:		Finance
Bus Phone: 4026855314									
Prv Phone: (402)380-1495	Mob Phone:	402)380-1495				Pag	je:		2 of 2
Deliver To:									
KENNETH JOHNSON					Make/Mode	al: JOH	IN DEERE S690		
1210 COUNTY RD L									
OAKLAND NE 68045					Meter:	158	1		
					Serial Num	ber: 1H0	S690SAG078534	41	
					Ea ID:	SAG	30785341		
Bus Phone: (402)685-5314]] '				
Prv Phone: (402)380-1495	Mob Phone:	(402)380-1495			Fleet No:		W		
/LD Retail									
MILEAGESRV	MILEAGE - SER	/ICE VEH		35	.00	2.00	2.00	\$70.00	1
Labor: \$216.75	Parts: \$0.00	OL&M:	\$0.00	M	isc: \$70.00		Sub-Total:	\$286.75	
Bain a llamanua Chargoni									
Miscellaneous Charges: Service Accessories									\$24.16
		Finance Informati	ion			wr	Labor:		\$483.10
		Type: Multi-use A	cct US	Auth. No	: 675573		Parts:		\$151.92
		Merchant No: 48	3000244				OL&M:		\$0.00
N		Card No: XXXX	xxxxxxxx2	402			Misc:		\$94.16
		Bill Code: 705		COMBINE PA	RTS/SERVIO	CE	Sales Tax:		\$36.2
		Credit Plan: 249	_ PUF	RCHASE			Grand Total:		\$765.4
* * * DOCUMENT	COPY * * *						Grand Total.		*******


TERMS AND CONDITIONS

Repayment Terms:

This purchase(s) is subject to the terms of the Multi-Use Account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

Received by:	Date:
--------------	-------







Invoice To Account No: 133526

SERVICE INVOICE

KENNETH JOHNSON	Invoice Number:	2610612
1210 COUNTY RD L	Invoice Date:	10/24/2020
OAKLAND NE 68045	Location:	30
	Work Order Number:	460560
	Payment Type:	Finance
Bus Phone: 4026855314		4 - 60
Prv Phone: (402)380-1495 Mob Phone: (402)380-1495	Page:	1 of 2

Deliver To:

KENNETH JOHNSON 1210 COUNTY RD L OAKLAND NE 68045

Bus Phone: (402)685-5314

Prv Phone: (402)380-1495

Mob Phone: (402)380-1495

Make/Model:

JOHN DEERE S690

Meter:

950

Serial Number: 1H0S690SAG0785341

Eq ID:

SAG0785341

Fleet No:

/LD Retail COMPLAINT:

01 Service Call load & drive time

CORRECTION:

Service Call load & drive time

66 MILES ROUND TRIP X2

Miscellaneous	<u>Description</u>	VEH	Quantity	<u>List Price</u>	Net Price	Extended Price	Taxed Ind
MILEAGESRV	MILEAGE - SERVICE		35.00	2.00	2.00	\$70.00	N
Labor: \$303.96	Parts: \$0.00	OL&M: \$0.00	Misc: \$	70.00	Sub-To	otal: \$373.96	

Gen2- Retail

COMPLAINT:


Install business band radio and replace am/fm radio antenna

CORRECTION:

WENT OUT AND LOOKED AT CB AND MADE A PLAN ABOUT WHERE TO MOUNT IT. TRIED NEW ANTENNA QUICK BUT DID NOT CHANGE ANYTHING. WENT BACK OUT AND REMOVED FRONT ROOF FROM COMBINE. FOUND THAT ANTENNA BASE DID NOT HAVE CORRECT SIZE OF THREAD FOR ANTENNA CABLE. INSTALLED NEW BASE AND TESTED RADIO AND WORKED CLEAR. INSTALLED ROOF BACK DOWN. DRILLED HOLE IN CB BRACKET AND MOUNTED TO DUAL DISPLAY BRACKET. MOUNTED CB TO BRACKET. REMOVED RH REAR CORNER POST. PULLED OUT CB CABLE AND RAN TO CB. RAN SWITCHED POWER THROUGH POWER STRIP UNDER SEAT TO CB. SPLICED WIRES FROM CB POWER CABLE TO POWER STRIP CABLE TO HIDE IT IN CORNER POST AND ROOF. MOUNTED MIC AND MIC HOLDER TO CB.

<u>Part Number</u>	Description ELEC. CONN	Quantity	List Price	Net Price	Extended Price	Taxed Ind
57M10889		4.00	1.23	1.23	\$4.92	Y
AXE59442	Antenna	1.00	47.99	47.99	\$47.99	Υ








SERVICE INVOICE Invoice To Account No: 133526 2610612 Invoice Number: KENNETH JOHNSON 10/24/2020 1210 COUNTY RD L Invoice Date: OAKLAND NE 68045 Location: 30 Work Order Number: 460560 Finance Payment Type: Bus Phone: 4026855314 2 of 2 Page: Mob Phone: (402)380-1495 Prv Phone: (402)380-1495 Deliver To: JOHN DEERE S690 KENNETH JOHNSON Make/Model: 1210 COUNTY RD L OAKLAND NE 68045 Meter: 950 Serial Number: 1H0S690SAG0785341 Eq ID: SAG0785341 Bus Phone: (402)685-5314 Fleet No: Mob Phone: (402)380-1495 Prv Phone: (402)380-1495 Gen2- Retail 1.00 0.62 0.62 \$0.62 **HDWBLACK** Bulk Hardware, (\$/oz.) Black 10.9 Metric \$13.16 1.00 13.16 13.16 Std. Conn. With 3 foot Cable RE67013 List Price Net Price Extended Price Taxed Ind Quantity Miscellaneous <u>Description</u> 12.00 12.00 \$12.00 1.00 **FREIGHT** FREIGHT \$530.19 Misc: \$12.00 Sub-Total: Parts: \$66.69 OL&M: \$0.00 Labor: \$451.50 Miscellaneous Charges: \$37.77 Service Accessories **Finance Information** Labor: \$755.46 Type: Multi-use Acct US Auth. No: 953383 \$66.69 Parts: Merchant No: 48000244 \$0.00 OL&M: Card No: xxxxxxxxxxxx2402 \$119.77 Misc: JD COMBINE PARTS/SERVICE 705 Bill Code: \$47.95 Sales Tax: Credit Plan: 249 **PURCHASE** \$989.87 **Grand Total:** * * * DOCUMENT COPY * * *

TERMS AND CONDITIONS

This purchase(s) is subject to the terms of the Multi-Use Account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

·	
Received by:	Date:







Invoice To Account No: 133526

SERVICE INVOICE

KENNETH JOHNSON	Invoice Number:	2610617
1210 COUNTY RD L	Invoice Date:	10/24/2020
OAKLAND NE 68045	Location:	30
	Work Order Number:	461241
	Payment Type:	Finance
Bus Phone: 4026855314		
Prv Phone: (402)380-1495 Mob Phone: (402)380-1495	Page:	1 of 2

Deliver To:

KENNETH JOHNSON

1210 COUNTY RD L

OAKLAND NE 68045

Bus Phone: (402)685-5314

Make/Model: JOHN DEERE S690

Meter:

Serial Number: 1H0S690SAG0785341

Eq ID: SAG0785341

Fleet No:

/LD Retail

COMPLAINT:

01 Service Call load & drive time

Prv Phone: (402)380-1495

CORRECTION:

66 MILES ROUND TRIP

Miscellaneous	<u>Description</u>	VEH	Quantity	<u>List Price</u>	Net Price	Extended Price	<u>Taxed Ind</u>
MILEAGESRV	MILEAGE - SERVICE		35.00	2.00	2.00	\$70.00	N
Labor: \$277.91	Parts: \$0.00	OL&M: \$0.00	Misc: \$	\$70.00	Sub-To	otal: \$347.91	

Gen2- Retail

COMPLAINT:

Repair feed accelerator belt and stone trap door

CORRECTION:


RAISED FEEDERHOUSE. REMOVED MOUNTING SCREWS FOR FEED PLATE AND REMOVED FEED PLATE AND HINGE ASSEMBLY. ASSEMBLED NEW DOOR AND HINGE. INSTALLED ONTO MACHINE. WENT TO ADJUST FEED PLATE DOOR AND COULD NOT GET TO SEAT TIGHT. FOUND THAT LATCH ASSEMBLY WAS WORN. INSTALLED UPDATED HEAVY DUTY LATCH KIT AND ADJUSTED AND WAS ABLE TO ADJUST.

Mob Phone: (402)380-1495

REMOVED SHOE AUGER DRIVE BELT. REMOVED FRONT JACKSHAFT BELT. REMOVED BELT. ROUTED NEW FEED ACCELERATOR BELT. INSTALLED FRONT JACKSHAFT BELT. INSTALLED SHOE AUGER BELT.

Part Number AH156157	<u>Description</u> PLATE	Quantity 1.00	<u>List Price</u> 324.17	<u>Net Price</u> 324.17	Extended Price \$324.17	Taxed Ind Y
AH227675	HINGE	1.00	213.88	213.88	\$213.88	Υ
H130057	PIN FASTEN	1.00	95.31	95.31	\$95.31	Υ
HXE152482	V-BELT	1.00	155.51	155.51	\$155.51	Υ







\$2,895.74

Grand Total:

www.plattevalleyequipment.com

SERVICE INVOICE Invoice To Account No: 133526 KENNETH JOHNSON Invoice Number: 2610617 1210 COUNTY RD L Invoice Date: 10/24/2020 OAKLAND NE 68045 30 Location: 461241 Work Order Number: Finance Payment Type: Bus Phone: 4026855314 2 of 2 Prv Phone: (402)380-1495 Mob Phone: (402)380-1495 Page: Deliver To: JOHN DEERE S690 KENNETH JOHNSON Make/Model: 1210 COUNTY RD L OAKLAND NE 68045 Meter: Serial Number: 1H0S690SAG0785341 Eq ID: SAG0785341 Bus Phone: (402)685-5314 Fleet No: Prv Phone: (402)380-1495 Mob Phone: (402)380-1495 Gen2- Retail \$786.58 1.00 786.58 786.58 KXE10485 Latch Kit Sub-Total: \$2,348.02 Parts: \$1,575.45 OL&M: \$0.00 Misc: \$0.00 Labor: \$772.57 Miscellaneous Charges: \$52.52 Service Accessories Finance Information \$1,050.48 Labor: Type: Multi-use Acct US Auth. No: 953327 Parts: \$1,575.45 Merchant No: 48000244 OL&M: \$0.00 Card No: xxxxxxxxxxx2402 \$122.52 Misc: JD COMBINE PARTS/SERVICE Bill Code: 705 \$147.29 Sales Tax:

PURCHASE

TERMS AND CONDITIONS

* * * DOCUMENT COPY * * *

This purchase(s) is subject to the terms of the Multi-Use Account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money security interest, except as limited in that agreement, in the goods described.

Unused parts in new condition are returnable within 30 days of purchase and must be accompanied by this invoice. Returned parts are subject to a minimum 25% restocking fee. Open kits or electrical parts are not returnable. Please refer to our return policy for full details. Thank you for your business.

Received by:	Date:
--------------	-------

Credit Plan: 249